

FOTO SURVEY KONDISI JALAN TAHUN 2020

RUAS JALAN : Sangkalputung - Kalibagor



LOKASI : STA 0+000

KONDISI PERKERASAN : ASPAL

LEBAR PERKERASAN : 5 M

CATATAN : BAIK

LOKASI : STA 0+200

KONDISI PERKERASAN : ASPAL

LEBAR PERKERASAN : 5 M

CATATAN : BAIK

NO. RUAS	NAMA RUAS	DPU & PENATAAN RUANG KABUPATEN BANYUMAS	PETUGAS SURVEY	HALAMAN
141	Sangkalputung - Kalibagor		KHOLID - SANDI	1

FOTO SURVEY KONDISI JALAN TAHUN 2020

RUAS JALAN : Sangkalputung - Kalibagor



LOKASI : STA 0+400

KONDISI PERKERASAN : ASPAL

LEBAR PERKERASAN : 5 M

CATATAN : BAIK

LOKASI : STA 0+600

KONDISI PERKERASAN : ASPAL

LEBAR PERKERASAN : 5 M

CATATAN : SEDANG

NO. RUAS	NAMA RUAS	DPU & PENATAAN RUANG KABUPATEN BANYUMAS	PETUGAS SURVEY	HALAMAN
141	Sangkalputung - Kalibagor		KHOLID - SANDI	2

FOTO SURVEY KONDISI JALAN TAHUN 2020

RUAS JALAN : Sangkalputung - Kalibagor



LOKASI : STA 0+800

KONDISI PERKERASAN : ASPAL
LEBAR PERKERASAN : 5 M
CATATAN : SEDANG

LOKASI : STA 1+000

KONDISI PERKERASAN : ASPAL
LEBAR PERKERASAN : 5 M
CATATAN : SEDANG

NO. RUAS	NAMA RUAS	DPU & PENATAAN RUANG KABUPATEN BANYUMAS	PETUGAS SURVEY	HALAMAN
141	Sangkalputung - Kalibagor		KHOLID - SANDI	3

FOTO SURVEY KONDISI JALAN TAHUN 2020

RUAS JALAN : Sangkalputung - Kalibagor



LOKASI : STA 1+200

KONDISI PERKERASAN : ASPAL
LEBAR PERKERASAN : 5 M
CATATAN : BAIK

LOKASI : STA 1+400

KONDISI PERKERASAN : ASPAL
LEBAR PERKERASAN : 5 M
CATATAN : SEDANG

NO. RUAS	NAMA RUAS	DPU & PENATAAN RUANG KABUPATEN BANYUMAS	PETUGAS SURVEY	HALAMAN
141	Sangkalputung - Kalibagor		KHOLID - SANDI	4

FOTO SURVEY KONDISI JALAN TAHUN 2020

RUAS JALAN : Sangkalputung - Kalibagor



LOKASI : STA 1+600

KONDISI PERKERASAN : ASPAL
LEBAR PERKERASAN : 4 M
CATATAN : RUSAK RINGAN

LOKASI : STA 1+800

KONDISI PERKERASAN : ASPAL
LEBAR PERKERASAN : 4 M
CATATAN : SEDANG

NO. RUAS	NAMA RUAS	DPU & PENATAAN RUANG KABUPATEN BANYUMAS	PETUGAS SURVEY	HALAMAN
141	Sangkalputung - Kalibagor		KHOLID - SANDI	5

FOTO SURVEY KONDISI JALAN TAHUN 2020

RUAS JALAN : Sangkalputung - Kalibagor



LOKASI : STA 2+000

KONDISI PERKERASAN : ASPAL
LEBAR PERKERASAN : 5 M
CATATAN : RUSAK RINGAN

LOKASI : STA 2+200

KONDISI PERKERASAN : ASPAL
LEBAR PERKERASAN : 5 M
CATATAN : RUSAK RINGAN

NO. RUAS	NAMA RUAS	DPU & PENATAAN RUANG KABUPATEN BANYUMAS	PETUGAS SURVEY	HALAMAN
141	Sangkalputung - Kalibagor		KHOLID - SANDI	6

FOTO SURVEY KONDISI JALAN TAHUN 2020

RUAS JALAN : Sangkalputung - Kalibagor



LOKASI : STA 2+400

KONDISI PERKERASAN : ASPAL
LEBAR PERKERASAN : 5 M
CATATAN : SEDANG

LOKASI : STA 2+600

KONDISI PERKERASAN : ASPAL
LEBAR PERKERASAN : 5 M
CATATAN : SEDANG

NO. RUAS	NAMA RUAS	DPU & PENATAAN RUANG KABUPATEN BANYUMAS	PETUGAS SURVEY	HALAMAN
141	Sangkalputung - Kalibagor		KHOLID - SANDI	7

FOTO SURVEY KONDISI JALAN TAHUN 2020

RUAS JALAN : Sangkalputung - Kalibagor



LOKASI : STA 2+800

KONDISI PERKERASAN : ASPAL
LEBAR PERKERASAN : 5 M
CATATAN : SEDANG

LOKASI : STA 3+000

KONDISI PERKERASAN : ASPAL
LEBAR PERKERASAN : 5 M
CATATAN : SEDANG

NO. RUAS	NAMA RUAS	DPU & PENATAAN RUANG KABUPATEN BANYUMAS	PETUGAS SURVEY	HALAMAN
141	Sangkalputung - Kalibagor		KHOLID - SANDI	8

FOTO SURVEY KONDISI JALAN TAHUN 2020

RUAS JALAN : Sangkalputung - Kalibagor



LOKASI : **STA 3+200**

KONDISI PERKERASAN : ASPAL

LEBAR PERKERASAN : 5 M

CATATAN : SEDANG

LOKASI : **STA 3+400**

KONDISI PERKERASAN : ASPAL

LEBAR PERKERASAN : 5 M

CATATAN : SEDANG

NO. RUAS	NAMA RUAS	DPU & PENATAAN RUANG KABUPATEN BANYUMAS	PETUGAS SURVEY	HALAMAN
141	Sangkalputung - Kalibagor		KHOLID - SANDI	9

FOTO SURVEY KONDISI JALAN TAHUN 2020

RUAS JALAN : Sangkalputung - Kalibagor



LOKASI : **STA 3+600**

KONDISI PERKERASAN : ASPAL

LEBAR PERKERASAN : 5 M

CATATAN : SEDANG

LOKASI : **STA 3+800**

KONDISI PERKERASAN : ASPAL

LEBAR PERKERASAN : 5 M

CATATAN : SEDANG

NO. RUAS	NAMA RUAS	DPU & PENATAAN RUANG KABUPATEN BANYUMAS	PETUGAS SURVEY	HALAMAN
141	Sangkalputung - Kalibagor		KHOLID - SANDI	10

FOTO SURVEY KONDISI JALAN TAHUN 2020

RUAS JALAN : Sangkalputung - Kalibagor



LOKASI : **STA 4+000**

KONDISI PERKERASAN : ASPAL

LEBAR PERKERASAN : 5 M

CATATAN : SEDANG

NO. RUAS	NAMA RUAS	DPU & PENATAAN RUANG	PETUGAS SURVEY	HALAMAN
141	Sangkalputung - Kalibagor	KABUPATEN BANYUMAS	KHOLID - SANDI	11