

FOTO SURVEY KONDISI JALAN TAHUN 2020

RUAS JALAN : Cikawung - Cibangkong



LOKASI : STA 0+000

KONDISI PERKERASAN : ASPAL

LEBAR PERKERASAN : 3.5 M

CATATAN : BAIK

LOKASI : STA 0+200

KONDISI PERKERASAN : ASPAL

LEBAR PERKERASAN : 3.5 M

CATATAN : BAIK

NO. RUAS	NAMA RUAS	DPU & PENATAAN RUANG KABUPATEN BANYUMAS	PETUGAS SURVEY	HALAMAN
286	Cikawung - Cibangkong		KHOLID - SANDI	1

FOTO SURVEY KONDISI JALAN TAHUN 2020

RUAS JALAN : Cikawung - Cibangkong



LOKASI : STA 0+400

KONDISI PERKERASAN : KERIKIL

LEBAR PERKERASAN : 3.5 M

CATATAN : RUSAK BERAT

LOKASI : STA 0+600

KONDISI PERKERASAN : ASPAL

LEBAR PERKERASAN : 3.5 M

CATATAN : BAIK

NO. RUAS	NAMA RUAS	DPU & PENATAAN RUANG KABUPATEN BANYUMAS	PETUGAS SURVEY	HALAMAN
286	Cikawung - Cibangkong		KHOLID - SANDI	2

FOTO SURVEY KONDISI JALAN TAHUN 2020

RUAS JALAN : Cikawung - Cibangkong



LOKASI : STA 0+800

KONDISI PERKERASAN : ASPAL
LEBAR PERKERASAN : 3.5 M
CATATAN : BAIK

LOKASI : STA 1+000

KONDISI PERKERASAN : KERIKIL
LEBAR PERKERASAN : 3.5 M
CATATAN : RUSAK BERAT

NO. RUAS	NAMA RUAS	DPU & PENATAAN RUANG KABUPATEN BANYUMAS	PETUGAS SURVEY KHOLID - SANDI	HALAMAN
286	Cikawung - Cibangkong			3

FOTO SURVEY KONDISI JALAN TAHUN 2020

RUAS JALAN : Cikawung - Cibangkong



LOKASI : STA 1+200

KONDISI PERKERASAN : ASPAL
LEBAR PERKERASAN : 3.5 M
CATATAN : RUSAK RINGAN


LOKASI : STA 1+300

KONDISI PERKERASAN : KERIKIL
LEBAR PERKERASAN : 3.5 M
CATATAN : RUSAK BERAT

NO. RUAS	NAMA RUAS	DPU & PENATAAN RUANG KABUPATEN BANYUMAS	PETUGAS SURVEY KHOLID - SANDI	HALAMAN
286	Cikawung - Cibangkong			4

FOTO SURVEY KONDISI JALAN TAHUN 2020

RUAS JALAN : Cikawung - Cibangkong



LOKASI : **STA 1+400**

KONDISI PERKERASAN : KERIKIL

LEBAR PERKERASAN : 3.5 M

CATATAN : RUSAK BERAT

NO. RUAS	NAMA RUAS	DPU & PENATAAN RUANG	PETUGAS SURVEY	HALAMAN
286	Cikawung - Cibangkong	KABUPATEN BANYUMAS	KHOLID - SANDI	5