

FOTO SURVEY KONDISI JALAN TAHUN 2020

RUAS JALAN : Karangtalun Lor - Wlahar



LOKASI : STA 0+000

KONDISI PERKERASAN : ASPAL
LEBAR PERKERASAN : 3.5 M
CATATAN : BAIK

LOKASI : STA 0+200

KONDISI PERKERASAN : ASPAL
LEBAR PERKERASAN : 3.5 M
CATATAN : RUSAK RINGAN

NO. RUAS	NAMA RUAS	DPU & PENATAAN RUANG	PETUGAS SURVEY	HALAMAN
297	Karangtalun Lor - Wlahar	KABUPATEN BANYUMAS	KODHI - REZA	1

FOTO SURVEY KONDISI JALAN TAHUN 2020

RUAS JALAN : Karangtalun Lor - Wlahar



LOKASI : STA 0+400

KONDISI PERKERASAN : KERIKIL
LEBAR PERKERASAN : 3.5 M
CATATAN : RUSAK BERAT

LOKASI : STA 0+600

KONDISI PERKERASAN : KERIKIL
LEBAR PERKERASAN : 3.5 M
CATATAN : RUSAK BERAT

NO. RUAS	NAMA RUAS	DPU & PENATAAN RUANG	PETUGAS SURVEY	HALAMAN
297	Karangtalun Lor - Wlahar	KABUPATEN BANYUMAS	KODHI - REZA	2

FOTO SURVEY KONDISI JALAN TAHUN 2020

RUAS JALAN : Karangtalun Lor - Wlahar



LOKASI : STA 0+800

KONDISI PERKERASAN : ASPAL
LEBAR PERKERASAN : 3.5 M
CATATAN : RUSAK RINGAN

LOKASI : STA 1+000

KONDISI PERKERASAN : ASPAL
LEBAR PERKERASAN : 3.5 M
CATATAN : RUSAK RINGAN

NO. RUAS	NAMA RUAS	DPU & PENATAAN RUANG	PETUGAS SURVEY	HALAMAN
297	Karangtalun Lor - Wlahar	KABUPATEN BANYUMAS	KODHI - REZA	3

FOTO SURVEY KONDISI JALAN TAHUN 2020

RUAS JALAN : Karangtalun Lor - Wlahar



LOKASI : STA 1+200

KONDISI PERKERASAN : ASPAL
LEBAR PERKERASAN : 3.5 M
CATATAN : RUSAK RINGAN

LOKASI : STA 1+400

KONDISI PERKERASAN : ASPAL
LEBAR PERKERASAN : 3.5 M
CATATAN : RUSAK RINGAN

NO. RUAS	NAMA RUAS	DPU & PENATAAN RUANG	PETUGAS SURVEY	HALAMAN
297	Karangtalun Lor - Wlahar	KABUPATEN BANYUMAS	KODHI - REZA	4

FOTO SURVEY KONDISI JALAN TAHUN 2020

RUAS JALAN : Karangtalun Lor - Wlahar



LOKASI : STA 1+600

KONDISI PERKERASAN : ASPAL
LEBAR PERKERASAN : 3.5 M
CATATAN : RUSAK RINGAN



LOKASI : STA 1+800

KONDISI PERKERASAN : ASPAL
LEBAR PERKERASAN : 3.5 M
CATATAN : RUSAK RINGAN

NO. RUAS	NAMA RUAS	DPU & PENATAAN RUANG	PETUGAS SURVEY	HALAMAN
297	Karangtalun Lor - Wlahar	KABUPATEN BANYUMAS	KODHI - REZA	5

FOTO SURVEY KONDISI JALAN TAHUN 2020

RUAS JALAN : Karangtalun Lor - Wlahar



LOKASI : STA 2+000

KONDISI PERKERASAN : ASPAL
LEBAR PERKERASAN : 3.5 M
CATATAN : BAIK



LOKASI : STA 2+200

KONDISI PERKERASAN : ASPAL
LEBAR PERKERASAN : 3.5 M
CATATAN : BAIK

NO. RUAS	NAMA RUAS	DPU & PENATAAN RUANG	PETUGAS SURVEY	HALAMAN
297	Karangtalun Lor - Wlahar	KABUPATEN BANYUMAS	KODHI - REZA	6

FOTO SURVEY KONDISI JALAN TAHUN 2020

RUAS JALAN : Karangtalun Lor - Wlahar



LOKASI : **STA 2+400**

KONDISI PERKERASAN : ASPAL
LEBAR PERKERASAN : 3.5 M
CATATAN : BAIK



LOKASI : **STA 2+600**

KONDISI PERKERASAN : ASPAL
LEBAR PERKERASAN : 3.5 M
CATATAN : BAIK

NO. RUAS	NAMA RUAS	DPU & PENATAAN RUANG	PETUGAS SURVEY	HALAMAN
297	Karangtalun Lor - Wlahar	KABUPATEN BANYUMAS	KODHI - REZA	7

FOTO SURVEY KONDISI JALAN TAHUN 2020

RUAS JALAN : Karangtalun Lor - Wlahar



LOKASI : **STA 2+800**

KONDISI PERKERASAN : ASPAL
LEBAR PERKERASAN : 3.5 M
CATATAN : BAIK



LOKASI : **STA 3+000**

KONDISI PERKERASAN : KERIKIL
LEBAR PERKERASAN : 3.5 M
CATATAN : RUSAK BERAT

NO. RUAS	NAMA RUAS	DPU & PENATAAN RUANG	PETUGAS SURVEY	HALAMAN
297	Karangtalun Lor - Wlahar	KABUPATEN BANYUMAS	KODHI - REZA	8

FOTO SURVEY KONDISI JALAN TAHUN 2020

RUAS JALAN : Karangtalun Lor - Wlahar



LOKASI : **STA 3+200**

KONDISI PERKERASAN : ASPAL
LEBAR PERKERASAN : 3.5 M
CATATAN : SEDANG

LOKASI : **STA 3+400**

KONDISI PERKERASAN : ASPAL
LEBAR PERKERASAN : 3.5 M
CATATAN : BAIK

NO. RUAS	NAMA RUAS	DPU & PENATAAN RUANG	PETUGAS SURVEY	HALAMAN
297	Karangtalun Lor - Wlahar	KABUPATEN BANYUMAS	KODHI - REZA	9

FOTO SURVEY KONDISI JALAN TAHUN 2020

RUAS JALAN : Karangtalun Lor - Wlahar



LOKASI : **STA 3+600**

KONDISI PERKERASAN : ASPAL
LEBAR PERKERASAN : 3.5 M
CATATAN : BAIK

LOKASI : **STA 3+800**

KONDISI PERKERASAN : ASPAL
LEBAR PERKERASAN : 3.5 M
CATATAN : BAIK

NO. RUAS	NAMA RUAS	DPU & PENATAAN RUANG	PETUGAS SURVEY	HALAMAN
297	Karangtalun Lor - Wlahar	KABUPATEN BANYUMAS	KODHI - REZA	10

FOTO SURVEY KONDISI JALAN TAHUN 2020

RUAS JALAN : Karangtalun Lor - Wlahar



LOKASI : **STA 4+000**

KONDISI PERKERASAN : ASPAL
LEBAR PERKERASAN : 3.5 M
CATATAN : BAIK

LOKASI : **STA 4+200**

KONDISI PERKERASAN : ASPAL
LEBAR PERKERASAN : 3.5 M
CATATAN : BAIK

NO. RUAS	NAMA RUAS	DPU & PENATAAN RUANG	PETUGAS SURVEY	HALAMAN
297	Karangtalun Lor - Wlahar	KABUPATEN BANYUMAS	KODHI - REZA	11

FOTO SURVEY KONDISI JALAN TAHUN 2020

RUAS JALAN : Karangtalun Lor - Wlahar



LOKASI : **STA 4+400**

KONDISI PERKERASAN : ASPAL
LEBAR PERKERASAN : 3.5 M
CATATAN : BAIK

LOKASI : **STA 4+600**

KONDISI PERKERASAN : ASPAL
LEBAR PERKERASAN : 3.5 M
CATATAN : SEDANG

NO. RUAS	NAMA RUAS	DPU & PENATAAN RUANG	PETUGAS SURVEY	HALAMAN
297	Karangtalun Lor - Wlahar	KABUPATEN BANYUMAS	KODHI - REZA	12

FOTO SURVEY KONDISI JALAN TAHUN 2020

RUAS JALAN : Karangtalun Lor - Wlahar



LOKASI : STA 4+800

KONDISI PERKERASAN : ASPAL
LEBAR PERKERASAN : 3.5 M
CATATAN : BAIK


LOKASI : STA 5+000

KONDISI PERKERASAN : ASPAL
LEBAR PERKERASAN : 3.5 M
CATATAN : BAIK

NO. RUAS	NAMA RUAS	DPU & PENATAAN RUANG KABUPATEN BANYUMAS	PETUGAS SURVEY	HALAMAN
297	Karangtalun Lor - Wlahar		KODHI - REZA	13

FOTO SURVEY KONDISI JALAN TAHUN 2020

RUAS JALAN : Karangtalun Lor - Wlahar



LOKASI : STA 5+200

KONDISI PERKERASAN : ASPAL
LEBAR PERKERASAN : 3.5 M
CATATAN : BAIK

LOKASI : STA 5+400

KONDISI PERKERASAN : ASPAL
LEBAR PERKERASAN : 3.5 M
CATATAN : BAIK

NO. RUAS	NAMA RUAS	DPU & PENATAAN RUANG KABUPATEN BANYUMAS	PETUGAS SURVEY	HALAMAN
297	Karangtalun Lor - Wlahar		KODHI - REZA	14

FOTO SURVEY KONDISI JALAN TAHUN 2020

RUAS JALAN : Karangtalun Lor - Wlahar



LOKASI : **STA 5+600**

KONDISI PERKERASAN : ASPAL
LEBAR PERKERASAN : 3.5 M
CATATAN : SEDANG



LOKASI : **STA 5+800**

KONDISI PERKERASAN : ASPAL
LEBAR PERKERASAN : 3.5 M
CATATAN : RUSAK RINGAN

NO. RUAS	NAMA RUAS	DPU & PENATAAN RUANG	PETUGAS SURVEY	HALAMAN
297	Karangtalun Lor - Wlahar	KABUPATEN BANYUMAS	KODHI - REZA	15

FOTO SURVEY KONDISI JALAN TAHUN 2020

RUAS JALAN : Karangtalun Lor - Wlahar



LOKASI : **STA 6+000**

KONDISI PERKERASAN : KERIKIL
LEBAR PERKERASAN : 3.5 M
CATATAN : RUSAK BERAT



LOKASI : **STA 6+200**

KONDISI PERKERASAN : KERIKIL
LEBAR PERKERASAN : 3.5 M
CATATAN : RUSAK BERAT

NO. RUAS	NAMA RUAS	DPU & PENATAAN RUANG	PETUGAS SURVEY	HALAMAN
297	Karangtalun Lor - Wlahar	KABUPATEN BANYUMAS	KODHI - REZA	16

FOTO SURVEY KONDISI JALAN TAHUN 2020

RUAS JALAN : Karangtalun Lor - Wlahar



LOKASI : **STA 6+400**

KONDISI PERKERASAN : ASPAL
LEBAR PERKERASAN : 3.5 M
CATATAN : BAIK

LOKASI : **STA 6+600**

KONDISI PERKERASAN : ASPAL
LEBAR PERKERASAN : 3.5 M
CATATAN : RUSAK RINGAN

NO. RUAS	NAMA RUAS	DPU & PENATAAN RUANG	PETUGAS SURVEY	HALAMAN
297	Karangtalun Lor - Wlahar	KABUPATEN BANYUMAS	KODHI - REZA	17

FOTO SURVEY KONDISI JALAN TAHUN 2020

RUAS JALAN : Karangtalun Lor - Wlahar



LOKASI : **STA 6+800**

KONDISI PERKERASAN : KERIKIL
LEBAR PERKERASAN : 3.5 M
CATATAN : RUSAK BERAT

LOKASI : **STA 7+000**

KONDISI PERKERASAN : KERIKIL
LEBAR PERKERASAN : 3.5 M
CATATAN : RUSAK BERAT

NO. RUAS	NAMA RUAS	DPU & PENATAAN RUANG	PETUGAS SURVEY	HALAMAN
297	Karangtalun Lor - Wlahar	KABUPATEN BANYUMAS	KODHI - REZA	18

FOTO SURVEY KONDISI JALAN TAHUN 2020

RUAS JALAN : Karangtalun Lor - Wlahar



LOKASI : STA 7+200

KONDISI PERKERASAN : ASPAL
LEBAR PERKERASAN : 3.5 M
CATATAN : RUSAK RINGAN



LOKASI : STA 7+400

KONDISI PERKERASAN : KERIKIL
LEBAR PERKERASAN : 3.5 M
CATATAN : RUSAK BERAT

NO. RUAS	NAMA RUAS	DPU & PENATAAN RUANG	PETUGAS SURVEY	HALAMAN
297	Karangtalun Lor - Wlahar	KABUPATEN BANYUMAS	KODHI - REZA	19

FOTO SURVEY KONDISI JALAN TAHUN 2020

RUAS JALAN : Karangtalun Lor - Wlahar



LOKASI : STA 7+600 - 7+700

KONDISI PERKERASAN : ASPAL
LEBAR PERKERASAN : 3.5 M
CATATAN : RUSAK RINGAN



LOKASI : STA 7+700 - 7+750

KONDISI PERKERASAN : ASPAL
LEBAR PERKERASAN : 3.5 M
CATATAN : SEDANG

NO. RUAS	NAMA RUAS	DPU & PENATAAN RUANG	PETUGAS SURVEY	HALAMAN
297	Karangtalun Lor - Wlahar	KABUPATEN BANYUMAS	KODHI - REZA	20