

FOTO SURVEY KONDISI JALAN TAHUN 2020

RUAS JALAN : Jl. RA Wiryaatmaja



LOKASI : STA 0+000

KONDISI PERKERASAN : ASPAL
LEBAR PERKERASAN : 11 M
CATATAN : BAIK


LOKASI : STA 0+200

KONDISI PERKERASAN : ASPAL
LEBAR PERKERASAN : 11 M
CATATAN : SEDANG

NO. RUAS	NAMA RUAS	DPU & PENATAAN RUANG	PETUGAS SURVEY	HALAMAN
320	Jl. RA Wiryaatmaja	KABUPATEN BANYUMAS	KHOLID - SANDI	1

FOTO SURVEY KONDISI JALAN TAHUN 2020

RUAS JALAN : Jl. RA Wiryaatmaja



LOKASI : STA 0+400

KONDISI PERKERASAN : ASPAL
LEBAR PERKERASAN : 11 M
CATATAN : SEDANG

LOKASI : STA 0+590

KONDISI PERKERASAN : ASPAL
LEBAR PERKERASAN : 11 M
CATATAN : SEDANG

NO. RUAS	NAMA RUAS	DPU & PENATAAN RUANG	PETUGAS SURVEY	HALAMAN
320	Jl. RA Wiryaatmaja	KABUPATEN BANYUMAS	KHOLID - SANDI	2