

FOTO SURVEY KONDISI JALAN TAHUN 2020

RUAS JALAN : Brigjend. H.M Bahrn



LOKASI : **STA 0+000**

KONDISI PERKERASAN : ASPAL
LEBAR PERKERASAN : 7 M
CATATAN : BAIK



LOKASI : **STA 0+200**

KONDISI PERKERASAN : ASPAL
LEBAR PERKERASAN : 7 M
CATATAN : SEDANG

NO. RUAS	NAMA RUAS	DPU & PENATAAN RUANG	PETUGAS SURVEY	HALAMAN
441	Brigjend. H.M Bahrn	KABUPATEN BANYUMAS	KODHI - REZA	1

FOTO SURVEY KONDISI JALAN TAHUN 2020

RUAS JALAN : Brigjend. H.M Bahrn



LOKASI : **STA 0+400**

KONDISI PERKERASAN : ASPAL
LEBAR PERKERASAN : 7 M
CATATAN : SEDANG



LOKASI : **STA 0+600**

KONDISI PERKERASAN : ASPAL
LEBAR PERKERASAN : 7 M
CATATAN : BAIK

NO. RUAS	NAMA RUAS	DPU & PENATAAN RUANG	PETUGAS SURVEY	HALAMAN
441	Brigjend. H.M Bahrn	KABUPATEN BANYUMAS	KODHI - REZA	2

FOTO SURVEY KONDISI JALAN TAHUN 2020

RUAS JALAN : Brigjend. H.M Bahrn



LOKASI : STA 0+800

KONDISI PERKERASAN : ASPAL
LEBAR PERKERASAN : 7 M
CATATAN : BAIK



LOKASI : STA 1+000

KONDISI PERKERASAN : ASPAL
LEBAR PERKERASAN : 7 M
CATATAN : BAIK

NO. RUAS	NAMA RUAS	DPU & PENATAAN RUANG KABUPATEN BANYUMAS	PETUGAS SURVEY	HALAMAN
441	Brigjend. H.M Bahrn		KODHI - REZA	3

FOTO SURVEY KONDISI JALAN TAHUN 2020

RUAS JALAN : Brigjend. H.M Bahrn



LOKASI : STA 1+200

KONDISI PERKERASAN : ASPAL
LEBAR PERKERASAN : 7 M
CATATAN : BAIK



LOKASI : STA 1+200 - 1+230

KONDISI PERKERASAN : ASPAL
LEBAR PERKERASAN : 7 M
CATATAN : SEDANG

NO. RUAS	NAMA RUAS	DPU & PENATAAN RUANG KABUPATEN BANYUMAS	PETUGAS SURVEY	HALAMAN
441	Brigjend. H.M Bahrn		KODHI - REZA	4