

FOTO SURVEY KONDISI JALAN TAHUN 2020

RUAS JALAN : H Madrani



LOKASI : STA 0+000

KONDISI PERKERASAN : ASPAL
LEBAR PERKERASAN : 4 M
CATATAN : SEDANG


LOKASI : STA 0+200

KONDISI PERKERASAN : ASPAL
LEBAR PERKERASAN : 4 M
CATATAN : SEDANG

NO. RUAS	NAMA RUAS	DPU & PENATAAN RUANG KABUPATEN BANYUMAS	PETUGAS SURVEY	HALAMAN
468	H Madrani		KODHI - REZA	1

FOTO SURVEY KONDISI JALAN TAHUN 2020

RUAS JALAN : H Madrani



LOKASI : STA 0+400

KONDISI PERKERASAN : ASPAL
LEBAR PERKERASAN : 4 M
CATATAN : BAIK

LOKASI : STA 0+450

KONDISI PERKERASAN : ASPAL
LEBAR PERKERASAN : 4 M
CATATAN : BAIK

NO. RUAS	NAMA RUAS	DPU & PENATAAN RUANG KABUPATEN BANYUMAS	PETUGAS SURVEY	HALAMAN
468	H Madrani		KODHI - REZA	2