

FOTO SURVEY KONDISI JALAN TAHUN 2020

RUAS JALAN : Mersi - Pamijen



LOKASI : STA 0+000

KONDISI PERKERASAN : ASPAL
LEBAR PERKERASAN : 3,5 M
CATATAN : BAIK

LOKASI : STA 0+200

KONDISI PERKERASAN : ASPAL
LEBAR PERKERASAN : 3,5 M
CATATAN : BAIK

NO. RUAS	NAMA RUAS	DPU & PENATAAN RUANG KABUPATEN BANYUMAS	PETUGAS SURVEY	HALAMAN
499	Mersi - Pamijen		KHOLID - SANDI	1

FOTO SURVEY KONDISI JALAN TAHUN 2020

RUAS JALAN : Mersi - Pamijen



LOKASI : STA 0+400

KONDISI PERKERASAN : ASPAL
LEBAR PERKERASAN : 3,5 M
CATATAN : RUSAK RINGAN

LOKASI : STA 0+600

KONDISI PERKERASAN : ASPAL
LEBAR PERKERASAN : 3,5 M
CATATAN : RUSAK RINGAN

NO. RUAS	NAMA RUAS	DPU & PENATAAN RUANG KABUPATEN BANYUMAS	PETUGAS SURVEY	HALAMAN
499	Mersi - Pamijen		KHOLID - SANDI	2

FOTO SURVEY KONDISI JALAN TAHUN 2020

RUAS JALAN : Mersi - Pamijen



LOKASI : **STA** **0+800 -** **0+810**

KONDISI PERKERASAN : ASPAL
LEBAR PERKERASAN : 3,5 M
CATATAN : RUSAK RINGAN

NO. RUAS	NAMA RUAS	DPU & PENATAAN RUANG KABUPATEN BANYUMAS	PETUGAS SURVEY	HALAMAN
499	Mersi - Pamijen		KHOLID - SANDI	3