

FOTO SURVEY KONDISI JALAN TAHUN 2020

RUAS JALAN : Bougenvil



LOKASI : STA 0+000

KONDISI PERKERASAN : ASPAL

LEBAR PERKERASAN : 3 M

CATATAN : BAIK

LOKASI : STA 0+200

KONDISI PERKERASAN : ASPAL

LEBAR PERKERASAN : 3 M

CATATAN : BAIK

NO. RUAS	NAMA RUAS	DPU & PENATAAN RUANG KABUPATEN BANYUMAS	PETUGAS SURVEY	HALAMAN
640	Bougenvil		KODHI - REZA	1

FOTO SURVEY KONDISI JALAN TAHUN 2020

RUAS JALAN : Bougenvil



LOKASI : STA 0+400

KONDISI PERKERASAN : ASPAL

LEBAR PERKERASAN : 3 M

CATATAN : BAIK

LOKASI : STA 0+550

KONDISI PERKERASAN : ASPAL

LEBAR PERKERASAN : 3 M

CATATAN : BAIK

NO. RUAS	NAMA RUAS	DPU & PENATAAN RUANG KABUPATEN BANYUMAS	PETUGAS SURVEY	HALAMAN
640	Bougenvil		KODHI - REZA	2