

FOTO SURVEY KONDISI JALAN TAHUN 2020

RUAS JALAN : Cipete - Banjarsari



LOKASI : STA 0+000

KONDISI PERKERASAN : ASPAL

LEBAR PERKERASAN : 3-4 M

CATATAN : SEDANG



LOKASI : STA 0+200

KONDISI PERKERASAN : ASPAL

LEBAR PERKERASAN : 3-4 M

CATATAN : RUSAK RINGAN

NO. RUAS	NAMA RUAS	DPU & PENATAAN RUANG KABUPATEN BANYUMAS	PETUGAS SURVEY	HALAMAN
8	Cipete - Banjarsari		KHOLID - SANDI	1

FOTO SURVEY KONDISI JALAN TAHUN 2020

RUAS JALAN : Cipete - Banjarsari



LOKASI : STA 0+400

KONDISI PERKERASAN : ASPAL

LEBAR PERKERASAN : 3-4 M

CATATAN : BAIK



LOKASI : STA 0+600

KONDISI PERKERASAN : KERIKIL

LEBAR PERKERASAN : 3-4 M

CATATAN : RUSAK BERAT

NO. RUAS	NAMA RUAS	DPU & PENATAAN RUANG KABUPATEN BANYUMAS	PETUGAS SURVEY	HALAMAN
8	Cipete - Banjarsari		KHOLID - SANDI	2

FOTO SURVEY KONDISI JALAN TAHUN 2020

RUAS JALAN : Cipete - Banjarsari



LOKASI : STA 0+800

KONDISI PERKERASAN : ASPAL

LEBAR PERKERASAN : 3-4 M

CATATAN : SEDANG



LOKASI : STA 1+000

KONDISI PERKERASAN : ASPAL

LEBAR PERKERASAN : 3-4 M

CATATAN : RUSAK RINGAN

NO. RUAS	NAMA RUAS	DPU & PENATAAN RUANG KABUPATEN BANYUMAS	PETUGAS SURVEY	HALAMAN
8	Cipete - Banjarsari		KHOLID - SANDI	3

FOTO SURVEY KONDISI JALAN TAHUN 2020

RUAS JALAN : Cipete - Banjarsari



LOKASI : STA 1+200

KONDISI PERKERASAN : ASPAL

LEBAR PERKERASAN : 3-4 M

CATATAN : SEDANG



LOKASI : STA 1+400

KONDISI PERKERASAN : ASPAL

LEBAR PERKERASAN : 3-4 M

CATATAN : RUSAK RINGAN

NO. RUAS	NAMA RUAS	DPU & PENATAAN RUANG KABUPATEN BANYUMAS	PETUGAS SURVEY	HALAMAN
8	Cipete - Banjarsari		KHOLID - SANDI	4

FOTO SURVEY KONDISI JALAN TAHUN 2020

RUAS JALAN : Cipete - Banjarsari



LOKASI : STA 1+600

KONDISI PERKERASAN : ASPAL
LEBAR PERKERASAN : 3-4 M
CATATAN : RUSAK RINGAN



LOKASI : STA 1+800

KONDISI PERKERASAN : ASPAL
LEBAR PERKERASAN : 3-4 M
CATATAN : RUSAK RINGAN

NO. RUAS	NAMA RUAS	DPU & PENATAAN RUANG KABUPATEN BANYUMAS	PETUGAS SURVEY	HALAMAN
8	Cipete - Banjarsari		KHOLID - SANDI	5

FOTO SURVEY KONDISI JALAN TAHUN 2020

RUAS JALAN : Cipete - Banjarsari



LOKASI : STA 2+000

KONDISI PERKERASAN : ASPAL
LEBAR PERKERASAN : 3-4 M
CATATAN : RUSAK RINGAN

NO. RUAS	NAMA RUAS	DPU & PENATAAN RUANG KABUPATEN BANYUMAS	PETUGAS SURVEY	HALAMAN
8	Cipete - Banjarsari		KHOLID - SANDI	6