

FOTO SURVEY KONDISI JALAN TAHUN 2020

RUAS JALAN : Cipete (Jombor) - Batuanten



LOKASI : STA 0+000

KONDISI PERKERASAN : ASPAL
LEBAR PERKERASAN : 4 M
CATATAN : BAIK


LOKASI : STA 0+200

KONDISI PERKERASAN : ASPAL
LEBAR PERKERASAN : 4 M
CATATAN : SEDANG

NO. RUAS	NAMA RUAS	DPU & PENATAAN RUANG KABUPATEN BANYUMAS	PETUGAS SURVEY	HALAMAN
92	Cipete (Jombor) - Batuanten		KHOLID - SANDI	1

FOTO SURVEY KONDISI JALAN TAHUN 2020

RUAS JALAN : Cipete (Jombor) - Batuanten



LOKASI : STA 0+400

KONDISI PERKERASAN : ASPAL
LEBAR PERKERASAN : 4 M
CATATAN : SEDANG

LOKASI : STA 0+600

KONDISI PERKERASAN : KERIKIL
LEBAR PERKERASAN : 4 M
CATATAN : RUSAK BERAT

NO. RUAS	NAMA RUAS	DPU & PENATAAN RUANG KABUPATEN BANYUMAS	PETUGAS SURVEY	HALAMAN
92	Cipete (Jombor) - Batuanten		KHOLID - SANDI	2

FOTO SURVEY KONDISI JALAN TAHUN 2020

RUAS JALAN : Cipete (Jombor) - Batuanten



LOKASI : **STA 0+800**

KONDISI PERKERASAN : ASPAL

LEBAR PERKERASAN : 4 M

CATATAN : SEDANG

LOKASI : **STA 1+000**

KONDISI PERKERASAN : KERIKIL

LEBAR PERKERASAN : 4 M

CATATAN : RUSAK BERAT

NO. RUAS	NAMA RUAS	DPU & PENATAAN RUANG KABUPATEN BANYUMAS	PETUGAS SURVEY	HALAMAN
92	Cipete (Jombor) - Batuanten		KHOLID - SANDI	3

FOTO SURVEY KONDISI JALAN TAHUN 2020

RUAS JALAN : Cipete (Jombor) - Batuanten



LOKASI : **STA 1+200**

KONDISI PERKERASAN : KERIKIL

LEBAR PERKERASAN : 4 M

CATATAN : RUSAK BERAT

LOKASI : **STA 1+400**

KONDISI PERKERASAN : ASPAL

LEBAR PERKERASAN : 4 M

CATATAN : BAIK

NO. RUAS	NAMA RUAS	DPU & PENATAAN RUANG KABUPATEN BANYUMAS	PETUGAS SURVEY	HALAMAN
92	Cipete (Jombor) - Batuanten		KHOLID - SANDI	4

FOTO SURVEY KONDISI JALAN TAHUN 2020

RUAS JALAN : Cipete (Jombor) - Batuanten



LOKASI : **STA 1+600**

KONDISI PERKERASAN : ASPAL

LEBAR PERKERASAN : 4 M

CATATAN : BAIK

LOKASI : **STA 1+700**

KONDISI PERKERASAN : ASPAL

LEBAR PERKERASAN : 4 M

CATATAN : BAIK

NO. RUAS	NAMA RUAS	DPU & PENATAAN RUANG KABUPATEN BANYUMAS	PETUGAS SURVEY	HALAMAN
92	Cipete (Jombor) - Batuanten		KHOLID - SANDI	5