

FOTO SURVEY KONDISI JALAN TAHUN 2022

RUAS JALAN : Krapyak-Ciwera



LOKASI : STA 0+000

KONDISI PERKERASAN : BAIK
LEBAR PERKERASAN : 4,2 M
CATATAN : ASPAL

LOKASI : STA 0+100

KONDISI PERKERASAN : SEDANG
LEBAR PERKERASAN : 4,2 M
CATATAN : ASPAL

NO. RUAS	NAMA RUAS	DPU KABUPATEN BANYUMAS	PETUGAS SURVEY	HALAMAN
254	Krapyak-Ciwera		YANU & INDRA	1

FOTO SURVEY KONDISI JALAN TAHUN 2022

RUAS JALAN : Krapyak-Ciwera



LOKASI : STA 0+200

KONDISI PERKERASAN : BAIK
LEBAR PERKERASAN : 4,2 M
CATATAN : ASPAL

LOKASI : STA 0+300

KONDISI PERKERASAN : RUSAK RINGAN
LEBAR PERKERASAN : 4,2 M
CATATAN : ASPAL

NO. RUAS	NAMA RUAS	DPU KABUPATEN BANYUMAS	PETUGAS SURVEY	HALAMAN
254	Krapyak-Ciwera		YANU & INDRA	2

FOTO SURVEY KONDISI JALAN TAHUN 2022

RUAS JALAN : Krpyak-Ciwera



LOKASI : **STA 0+400**

KONDISI PERKERASAN : RUSAK BERAT
LEBAR PERKERASAN : 4 M
CATATAN : BETON

LOKASI : **STA 0+450**

KONDISI PERKERASAN : RUSAK RINGAN
LEBAR PERKERASAN : 2,6 M
CATATAN : BETON

NO. RUAS	NAMA RUAS	DPU KABUPATEN BANYUMAS	PETUGAS SURVEY	HALAMAN
254	Krpyak-Ciwera		YANU & INDRA	3

FOTO SURVEY KONDISI JALAN TAHUN 2022

RUAS JALAN : Krpyak-Ciwera



LOKASI : **STA 0+500**

KONDISI PERKERASAN : RUSAK RINGAN
LEBAR PERKERASAN : 2,6 M
CATATAN : BETON

LOKASI : **STA 0+550**

KONDISI PERKERASAN : RUSAK BERAT
LEBAR PERKERASAN : 2,6 M
CATATAN : ASPAL

NO. RUAS	NAMA RUAS	DPU KABUPATEN BANYUMAS	PETUGAS SURVEY	HALAMAN
254	Krpyak-Ciwera		YANU & INDRA	4

FOTO SURVEY KONDISI JALAN TAHUN 2022

RUAS JALAN : Krapyak-Ciwera



LOKASI : STA 0+600

KONDISI PERKERASAN : RUSAK RINGAN

LEBAR PERKERASAN : 2,6 M

CATATAN : ASPAL

LOKASI : STA 0+700

KONDISI PERKERASAN : RUSAK RINGAN

LEBAR PERKERASAN : 2,6 M

CATATAN : ASPAL

NO. RUAS	NAMA RUAS	DPU KABUPATEN BANYUMAS	PETUGAS SURVEY	HALAMAN
254	Krapyak-Ciwera		YANU & INDRA	5

FOTO SURVEY KONDISI JALAN TAHUN 2022

RUAS JALAN : Krapyak-Ciwera



LOKASI : STA 0+740

KONDISI PERKERASAN : RUSAK BERAT

LEBAR PERKERASAN : 2,6 M

CATATAN : ASPAL

LOKASI : STA 0+800

KONDISI PERKERASAN : RUSAK BERAT

LEBAR PERKERASAN : 2,6 M

CATATAN : ASPAL

NO. RUAS	NAMA RUAS	DPU KABUPATEN BANYUMAS	PETUGAS SURVEY	HALAMAN
254	Krapyak-Ciwera		YANU & INDRA	6

FOTO SURVEY KONDISI JALAN TAHUN 2022

RUAS JALAN : Krapyak-Ciwera




LOKASI : **STA 0+900**

KONDISI PERKERASAN : RUSAK BERAT

LEBAR PERKERASAN : 2,6 M

CATATAN : ASPAL



LOKASI : **STA 1+000**

KONDISI PERKERASAN : RUSAK BERAT

LEBAR PERKERASAN : 2,6 M

CATATAN : ASPAL

NO. RUAS	NAMA RUAS	DPU KABUPATEN BANYUMAS	PETUGAS SURVEY	HALAMAN
254	Krapyak-Ciwera		YANU & INDRA	7

FOTO SURVEY KONDISI JALAN TAHUN 2022

RUAS JALAN : Krapyak-Ciwera



LOKASI : **STA 1+100**

KONDISI PERKERASAN : RUSAK BERAT

LEBAR PERKERASAN : 2,6 M

CATATAN : ASPAL



LOKASI : **STA 1+200**

KONDISI PERKERASAN : RUSAK BERAT

LEBAR PERKERASAN : 2,6 M

CATATAN : ASPAL

NO. RUAS	NAMA RUAS	DPU KABUPATEN BANYUMAS	PETUGAS SURVEY	HALAMAN
254	Krapyak-Ciwera		YANU & INDRA	8

FOTO SURVEY KONDISI JALAN TAHUN 2022

RUAS JALAN : Krapyak-Ciwera




LOKASI : STA 1+300

KONDISI PERKERASAN : RUSAK RINGAN

LEBAR PERKERASAN : 2,6 M

CATATAN : ASPAL



LOKASI : STA 1+400

KONDISI PERKERASAN : SEDANG

LEBAR PERKERASAN : 2,6 M

CATATAN : ASPAL

NO. RUAS	NAMA RUAS	DPU KABUPATEN BANYUMAS	PETUGAS SURVEY	HALAMAN
254	Krapyak-Ciwera		YANU & INDRA	9

FOTO SURVEY KONDISI JALAN TAHUN 2022

RUAS JALAN : Krapyak-Ciwera



LOKASI : STA 1+500

KONDISI PERKERASAN : RUSAK BERAT

LEBAR PERKERASAN : 2,6 M

CATATAN : ASPAL



LOKASI : STA 1+600

KONDISI PERKERASAN : RUSAK BERAT

LEBAR PERKERASAN : 2,6 M

CATATAN : ASPAL

NO. RUAS	NAMA RUAS	DPU KABUPATEN BANYUMAS	PETUGAS SURVEY	HALAMAN
254	Krapyak-Ciwera		YANU & INDRA	10

FOTO SURVEY KONDISI JALAN TAHUN 2022

RUAS JALAN : Krapyak-Ciwera



LOKASI : **STA 1+700**

KONDISI PERKERASAN : RUSAK BERAT

LEBAR PERKERASAN : 2,6 M

CATATAN : ASPAL



LOKASI : **STA 1+760**

KONDISI PERKERASAN : BAIK

LEBAR PERKERASAN : 2,6 M

CATATAN : ASPAL

NO. RUAS	NAMA RUAS	DPU KABUPATEN BANYUMAS	PETUGAS SURVEY	HALAMAN
254	Krapyak-Ciwera		YANU & INDRA	11

FOTO SURVEY KONDISI JALAN TAHUN 2022

RUAS JALAN : Krapyak-Ciwera



LOKASI : **STA 1+800**

KONDISI PERKERASAN : BAIK

LEBAR PERKERASAN : 2,6 M

CATATAN : ASPAL



LOKASI : **STA 1+870**

KONDISI PERKERASAN : RUSAK BERAT

LEBAR PERKERASAN : 2,6 M

CATATAN : ASPAL

NO. RUAS	NAMA RUAS	DPU KABUPATEN BANYUMAS	PETUGAS SURVEY	HALAMAN
254	Krapyak-Ciwera		YANU & INDRA	12

FOTO SURVEY KONDISI JALAN TAHUN 2022

RUAS JALAN : Krapyak-Ciwera



LOKASI : STA 1+900

KONDISI PERKERASAN : RUSAK BERAT
LEBAR PERKERASAN : 2,6 M
CATATAN : ASPAL



LOKASI : STA 2+000

KONDISI PERKERASAN : RUSAK BERAT
LEBAR PERKERASAN : 2,6 M
CATATAN : ASPAL

NO. RUAS	NAMA RUAS	DPU KABUPATEN BANYUMAS	PETUGAS SURVEY	HALAMAN
254	Krapyak-Ciwera		YANU & INDRA	13


FOTO SURVEY KONDISI JALAN TAHUN 2022

RUAS JALAN : Krapyak-Ciwera



LOKASI : STA 2+100

KONDISI PERKERASAN : RUSAK BERAT
LEBAR PERKERASAN : 2,2 M
CATATAN : ASPAL



LOKASI : STA 2+200

KONDISI PERKERASAN : RUSAK RINGAN
LEBAR PERKERASAN : 2,2 M
CATATAN : ASPAL

NO. RUAS	NAMA RUAS	DPU KABUPATEN BANYUMAS	PETUGAS SURVEY	HALAMAN
254	Krapyak-Ciwera		YANU & INDRA	14

FOTO SURVEY KONDISI JALAN TAHUN 2022

RUAS JALAN : Krapyak-Ciwera



LOKASI : STA 2+300

KONDISI PERKERASAN : RUSAK RINGAN
LEBAR PERKERASAN : 2,2 M
CATATAN : ASPAL



LOKASI : STA 2+400

KONDISI PERKERASAN : RUSAK BERAT
LEBAR PERKERASAN : 2 M
CATATAN : ASPAL

NO. RUAS	NAMA RUAS	DPU KABUPATEN BANYUMAS	PETUGAS SURVEY	HALAMAN
254	Krapyak-Ciwera		YANU & INDRA	15

FOTO SURVEY KONDISI JALAN TAHUN 2022

RUAS JALAN : Krapyak-Ciwera



LOKASI : STA 2+500

KONDISI PERKERASAN : RUSAK BERAT
LEBAR PERKERASAN : 2 M
CATATAN : ASPAL



LOKASI : STA 2+600

KONDISI PERKERASAN : RUSAK BERAT
LEBAR PERKERASAN : 2 M
CATATAN : Kerikil

NO. RUAS	NAMA RUAS	DPU KABUPATEN BANYUMAS	PETUGAS SURVEY	HALAMAN
254	Krapyak-Ciwera		YANU & INDRA	16

FOTO SURVEY KONDISI JALAN TAHUN 2022

RUAS JALAN : Krapyak-Ciwera



LOKASI : STA 2+700

KONDISI PERKERASAN : RUSAK BERAT
LEBAR PERKERASAN : 2 M
CATATAN : Kerikil



LOKASI : STA 2+800

KONDISI PERKERASAN : RUSAK BERAT
LEBAR PERKERASAN : 2,2 M
CATATAN : Kerikil

NO. RUAS	NAMA RUAS	DPU KABUPATEN BANYUMAS	PETUGAS SURVEY	HALAMAN
254	Krapyak-Ciwera		YANU & INDRA	17

FOTO SURVEY KONDISI JALAN TAHUN 2022

RUAS JALAN : Krapyak-Ciwera



LOKASI : STA 2+900

KONDISI PERKERASAN : RUSAK BERAT
LEBAR PERKERASAN : 2,2 M
CATATAN : Kerikil



LOKASI : STA 3+000

KONDISI PERKERASAN : RUSAK BERAT
LEBAR PERKERASAN : 3 M
CATATAN : Kerikil

NO. RUAS	NAMA RUAS	DPU KABUPATEN BANYUMAS	PETUGAS SURVEY	HALAMAN
254	Krapyak-Ciwera		YANU & INDRA	18

FOTO SURVEY KONDISI JALAN TAHUN 2022

RUAS JALAN : Krapyak-Ciwera



LOKASI : **STA 3+100**

KONDISI PERKERASAN : Baik

LEBAR PERKERASAN : 2,5 M

CATATAN : Aspal



LOKASI : **STA 3+200**

KONDISI PERKERASAN : Baik

LEBAR PERKERASAN : 2,5 M

CATATAN : Aspal

NO. RUAS	NAMA RUAS	DPU KABUPATEN BANYUMAS	PETUGAS SURVEY	HALAMAN
254	Krapyak-Ciwera		YANU & INDRA	19

FOTO SURVEY KONDISI JALAN TAHUN 2022

RUAS JALAN : Krapyak-Ciwera



LOKASI : **STA 3+300**

KONDISI PERKERASAN : Baik

LEBAR PERKERASAN : 2,5 M

CATATAN : Aspal



LOKASI : **STA 3+400**

KONDISI PERKERASAN : Baik

LEBAR PERKERASAN : 2,5 M

CATATAN : Aspal

NO. RUAS	NAMA RUAS	DPU KABUPATEN BANYUMAS	PETUGAS SURVEY	HALAMAN
254	Krapyak-Ciwera		YANU & INDRA	20

FOTO SURVEY KONDISI JALAN TAHUN 2022

RUAS JALAN : Krapyak-Ciwera



LOKASI : STA 3+460

KONDISI PERKERASAN : Rusak Berat
LEBAR PERKERASAN : 2,5 M
CATATAN : Aspal



LOKASI : STA 3+500

KONDISI PERKERASAN : Rusak Berat
LEBAR PERKERASAN : 2,5 M
CATATAN : Aspal

NO. RUAS	NAMA RUAS	DPU KABUPATEN BANYUMAS	PETUGAS SURVEY	HALAMAN
254	Krapyak-Ciwera		YANU & INDRA	21

FOTO SURVEY KONDISI JALAN TAHUN 2022

RUAS JALAN : Krapyak-Ciwera



LOKASI : STA 3+600

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 2,5 M
CATATAN : Aspal



LOKASI : STA 3+700

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 2,5 M
CATATAN : Aspal

NO. RUAS	NAMA RUAS	DPU KABUPATEN BANYUMAS	PETUGAS SURVEY	HALAMAN
254	Krapyak-Ciwera		YANU & INDRA	22

FOTO SURVEY KONDISI JALAN TAHUN 2022

RUAS JALAN : Krapyak-Ciwera



LOKASI : **STA 3+800**

KONDISI PERKERASAN : Baik

LEBAR PERKERASAN : 2,5 M

CATATAN : Aspal



LOKASI : **STA 3+900**

KONDISI PERKERASAN : Baik


LEBAR PERKERASAN : 2,5 M

CATATAN : Aspal

NO. RUAS	NAMA RUAS	DPU KABUPATEN BANYUMAS	PETUGAS SURVEY	HALAMAN
254	Krapyak-Ciwera		YANU & INDRA	23

FOTO SURVEY KONDISI JALAN TAHUN 2022

RUAS JALAN : Krapyak-Ciwera



LOKASI : **STA 4+000**

KONDISI PERKERASAN : Rusak Berat

LEBAR PERKERASAN : 2,5 M

CATATAN : Aspal



LOKASI : **STA 4+100**

KONDISI PERKERASAN : Rusak Berat

LEBAR PERKERASAN : 2,5 M

CATATAN : Aspal

NO. RUAS	NAMA RUAS	DPU KABUPATEN BANYUMAS	PETUGAS SURVEY	HALAMAN
254	Krapyak-Ciwera		YANU & INDRA	24

FOTO SURVEY KONDISI JALAN TAHUN 2022

RUAS JALAN : Krapyak-Ciwera



LOKASI : STA 4+200

KONDISI PERKERASAN : Rusak Berat
LEBAR PERKERASAN : 2,5 M
CATATAN : Aspal



LOKASI : STA 4+300

KONDISI PERKERASAN : Rusak Berat
LEBAR PERKERASAN : 2,5 M
CATATAN : Aspal

NO. RUAS	NAMA RUAS	DPU KABUPATEN BANYUMAS	PETUGAS SURVEY	HALAMAN
254	Krapyak-Ciwera		YANU & INDRA	25


FOTO SURVEY KONDISI JALAN TAHUN 2022

RUAS JALAN : Krapyak-Ciwera



LOKASI : STA 4+400

KONDISI PERKERASAN : Rusak Berat
LEBAR PERKERASAN : 2,5 M
CATATAN : Aspal



LOKASI : STA 4+500

KONDISI PERKERASAN : Rusak Berat
LEBAR PERKERASAN : 2,5 M
CATATAN : Aspal

NO. RUAS	NAMA RUAS	DPU KABUPATEN BANYUMAS	PETUGAS SURVEY	HALAMAN
254	Krapyak-Ciwera		YANU & INDRA	26

FOTO SURVEY KONDISI JALAN TAHUN 2022

RUAS JALAN : Krapyak-Ciwera




LOKASI : **STA 4+600**

KONDISI PERKERASAN : Rusak Berat

LEBAR PERKERASAN : 2,5 M

CATATAN : Aspal



LOKASI : **STA 4+700**

KONDISI PERKERASAN : Rusak Berat

LEBAR PERKERASAN : 2,5 M

CATATAN : Aspal

NO. RUAS	NAMA RUAS	DPU KABUPATEN BANYUMAS	PETUGAS SURVEY	HALAMAN
254	Krapyak-Ciwera		YANU & INDRA	27