

FOTO SURVEY KONDISI JALAN TAHUN 2022

RUAS JALAN : Cingebul-Karangjati



LOKASI : STA 0+000

KONDISI PERKERASAN : RUSAK BERAT

LEBAR PERKERASAN : 2.5 M

CATATAN : ASPAL

LOKASI : STA 0+100

KONDISI PERKERASAN : RUSAK BERAT

LEBAR PERKERASAN : 2.3 M

CATATAN : ASPAL

NO. RUAS	NAMA RUAS	DPU KABUPATEN BANYUMAS	PETUGAS SURVEY	HALAMAN
256	Cingebul-Karangjati		YANU & INDRA	1

FOTO SURVEY KONDISI JALAN TAHUN 2022

RUAS JALAN : Cingebul-Karangjati



LOKASI : STA 0+200

KONDISI PERKERASAN : RUSAK BERAT

LEBAR PERKERASAN : 2.3 M

CATATAN : ASPAL

LOKASI : STA 0+300

KONDISI PERKERASAN : RUSAK BERAT

LEBAR PERKERASAN : 2.3 M

CATATAN : ASPAL

NO. RUAS	NAMA RUAS	DPU KABUPATEN BANYUMAS	PETUGAS SURVEY	HALAMAN
256	Cingebul-Karangjati		YANU & INDRA	2

FOTO SURVEY KONDISI JALAN TAHUN 2022

RUAS JALAN : Cingebul-Karangjati



LOKASI : **STA 0+400**

KONDISI PERKERASAN : RUSAK BERAT
LEBAR PERKERASAN : 2.3 M
CATATAN : ASPAL


LOKASI : **STA 0+500**

KONDISI PERKERASAN : RUSAK BERAT
LEBAR PERKERASAN : 2.5 M
CATATAN : ASPAL

NO. RUAS	NAMA RUAS	DPU KABUPATEN BANYUMAS	PETUGAS SURVEY	HALAMAN
256	Cingebul-Karangjati		YANU & INDRA	3

FOTO SURVEY KONDISI JALAN TAHUN 2022

RUAS JALAN : Cingebul-Karangjati



LOKASI : **STA 0+600**

KONDISI PERKERASAN : RUSAK BERAT
LEBAR PERKERASAN : 2.5 M
CATATAN : BETON

LOKASI : **STA 0+700**

KONDISI PERKERASAN : RUSAK RINGAN
LEBAR PERKERASAN : 2.5 M
CATATAN : BETON

NO. RUAS	NAMA RUAS	DPU KABUPATEN BANYUMAS	PETUGAS SURVEY	HALAMAN
256	Cingebul-Karangjati		YANU & INDRA	4

FOTO SURVEY KONDISI JALAN TAHUN 2022

RUAS JALAN : Cingebul-Karangjati



LOKASI : **STA 0+800**

KONDISI PERKERASAN : RUSAK RINGAN
LEBAR PERKERASAN : 2.5 M
CATATAN : BETON


LOKASI : **STA 0+900**

KONDISI PERKERASAN : RUSAK RINGAN
LEBAR PERKERASAN : 2.5 M
CATATAN : BETON

NO. RUAS	NAMA RUAS	DPU KABUPATEN BANYUMAS	PETUGAS SURVEY	HALAMAN
256	Cingebul-Karangjati		YANU & INDRA	5

FOTO SURVEY KONDISI JALAN TAHUN 2022

RUAS JALAN : Cingebul-Karangjati



LOKASI : **STA 1+000**

KONDISI PERKERASAN : RUSAK RINGAN
LEBAR PERKERASAN : 2.5 M
CATATAN : BETON

LOKASI : **STA 1+100**

KONDISI PERKERASAN : RUSAK RINGAN
LEBAR PERKERASAN : 2.5 M
CATATAN : BETON

NO. RUAS	NAMA RUAS	DPU KABUPATEN BANYUMAS	PETUGAS SURVEY	HALAMAN
256	Cingebul-Karangjati		YANU & INDRA	6

FOTO SURVEY KONDISI JALAN TAHUN 2022

RUAS JALAN : Cingebul-Karangjati



LOKASI : STA 1+200

KONDISI PERKERASAN : SEDANG
LEBAR PERKERASAN : 2.5 M
CATATAN : BETON



LOKASI : STA 1+300

KONDISI PERKERASAN : SEDANG
LEBAR PERKERASAN : 2.5 M
CATATAN : BETON

NO. RUAS	NAMA RUAS	DPU KABUPATEN BANYUMAS	PETUGAS SURVEY	HALAMAN
256	Cingebul-Karangjati		YANU & INDRA	7

FOTO SURVEY KONDISI JALAN TAHUN 2022

RUAS JALAN : Cingebul-Karangjati



LOKASI : STA 1+400

KONDISI PERKERASAN : RUSAK RINGAN
LEBAR PERKERASAN : 2.5 M
CATATAN : BETON



LOKASI : STA 1+500

KONDISI PERKERASAN : SEDANG
LEBAR PERKERASAN : 2.5 M
CATATAN : BETON

NO. RUAS	NAMA RUAS	DPU KABUPATEN BANYUMAS	PETUGAS SURVEY	HALAMAN
256	Cingebul-Karangjati		YANU & INDRA	8

FOTO SURVEY KONDISI JALAN TAHUN 2022

RUAS JALAN : Cingebul-Karangjati



LOKASI : STA 1+600

KONDISI PERKERASAN : RUSAK RINGAN
LEBAR PERKERASAN : 2.5 M
CATATAN : ASPAL



LOKASI : STA 1+700

KONDISI PERKERASAN : RUSAK RINGAN
LEBAR PERKERASAN : 2.5 M
CATATAN : ASPAL

NO. RUAS	NAMA RUAS	DPU KABUPATEN BANYUMAS	PETUGAS SURVEY	HALAMAN
256	Cingebul-Karangjati		YANU & INDRA	9

FOTO SURVEY KONDISI JALAN TAHUN 2022

RUAS JALAN : Cingebul-Karangjati



LOKASI : STA 1+800

KONDISI PERKERASAN : SEDANG
LEBAR PERKERASAN : 2.5 M
CATATAN : ASPAL



LOKASI : STA 1+900

KONDISI PERKERASAN : BAIK
LEBAR PERKERASAN : 2.5 M
CATATAN : ASPAL

NO. RUAS	NAMA RUAS	DPU KABUPATEN BANYUMAS	PETUGAS SURVEY	HALAMAN
256	Cingebul-Karangjati		YANU & INDRA	10

FOTO SURVEY KONDISI JALAN TAHUN 2022

RUAS JALAN : Cingebul-Karangjati



LOKASI : STA 2+000

KONDISI PERKERASAN : RUSAK BERAT

LEBAR PERKERASAN : 2.5 M

CATATAN : ASPAL



LOKASI : STA 2+100

KONDISI PERKERASAN : SEDANG

LEBAR PERKERASAN : 2.5 M

CATATAN : ASPAL

NO. RUAS	NAMA RUAS	DPU KABUPATEN BANYUMAS	PETUGAS SURVEY	HALAMAN
256	Cingebul-Karangjati		YANU & INDRA	11

FOTO SURVEY KONDISI JALAN TAHUN 2022

RUAS JALAN : Cingebul-Karangjati



LOKASI : STA 2+200

KONDISI PERKERASAN : RUSAK BERAT

LEBAR PERKERASAN : 3 M

CATATAN : ASPAL



LOKASI : STA

KONDISI PERKERASAN :

LEBAR PERKERASAN : M

CATATAN :

NO. RUAS	NAMA RUAS	DPU KABUPATEN BANYUMAS	PETUGAS SURVEY	HALAMAN
256	Cingebul-Karangjati		YANU & INDRA	12