

FOTO SURVEY KONDISI JALAN TAHUN 2022

RUAS JALAN : KARANGMANGU-KETENGER



LOKASI : STA 0+000

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 3,2 M
CATATAN : Aspal

LOKASI : STA 0+100

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 3,5 M
CATATAN : Aspal

NO. RUAS	NAMA RUAS	DPU KABUPATEN BANYUMAS	PETUGAS SURVEY	HALAMAN
60	KARANGMANGU-KETENGER		KRESNA & GERA	1

FOTO SURVEY KONDISI JALAN TAHUN 2022

RUAS JALAN : KARANGMANGU-KETENGER



LOKASI : STA 0+200

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 3,5 M
CATATAN : Aspal

LOKASI : STA 0+300

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 3,5 M
CATATAN : Aspal

NO. RUAS	NAMA RUAS	DPU KABUPATEN BANYUMAS	PETUGAS SURVEY	HALAMAN
60	KARANGMANGU-KETENGER		KRESNA & BAYU	2

FOTO SURVEY KONDISI JALAN TAHUN 2022

RUAS JALAN : KARANGMANGU-KETENGER



LOKASI : **STA** **0+400**

KONDISI PERKERASAN : Baik

LEBAR PERKERASAN : 9 M

CATATAN : Aspal

LOKASI : **STA**

KONDISI PERKERASAN :

LEBAR PERKERASAN : M

CATATAN :

NO. RUAS	NAMA RUAS	DPU KABUPATEN BANYUMAS	PETUGAS SURVEY	HALAMAN
60	KARANGMANGU-KETENGER		KRESNA & BAYU	3