

FOTO SURVEY KONDISI JALAN TAHUN 2023

RUAS JALAN : JL. CIBERUNG (JEMB. TONJONG) - KRACAK



LOKASI : STA 0+000

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 4 M
CATATAN : Aspal

LOKASI : STA 0+100

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 4 M
CATATAN : Aspal

NO. RUAS	NAMA RUAS	DPU KABUPATEN BANYUMAS	PETUGAS SURVEY	HALAMAN
13	JL. CIBERUNG (JEMB. TONJONG) - KRACAK			1

FOTO SURVEY KONDISI JALAN TAHUN 2023

RUAS JALAN : JL. CIBERUNG (JEMB. TONJONG) - KRACAK



LOKASI : STA 0+200

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 4 M
CATATAN : Aspal

LOKASI : STA 0+300

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 4 M
CATATAN : Aspal

NO. RUAS	NAMA RUAS	DPU KABUPATEN BANYUMAS	PETUGAS SURVEY	HALAMAN
13	JL. CIBERUNG (JEMB. TONJONG) - KRACAK			2

FOTO SURVEY KONDISI JALAN TAHUN 2023

RUAS JALAN : JL. CIBERUNG (JEMB. TONJONG) - KRACAK



LOKASI : STA 0+400

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 4 M
CATATAN : Aspal

LOKASI : STA 0+500

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 4 M
CATATAN : Aspal

NO. RUAS	NAMA RUAS	DPU KABUPATEN BANYUMAS	PETUGAS SURVEY	HALAMAN
13	JL. CIBERUNG (JEMB. TONJONG) - KRACAK			3

FOTO SURVEY KONDISI JALAN TAHUN 2023

RUAS JALAN : JL. CIBERUNG (JEMB. TONJONG) - KRACAK



LOKASI : STA 0+600

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 4 M
CATATAN : Aspal

LOKASI : STA 0+700

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 4 M
CATATAN : Aspal

NO. RUAS	NAMA RUAS	DPU KABUPATEN BANYUMAS	PETUGAS SURVEY	HALAMAN
13	JL. CIBERUNG (JEMB. TONJONG) - KRACAK			4

FOTO SURVEY KONDISI JALAN TAHUN 2023

RUAS JALAN : JL. CIBERUNG (JEMB. TONJONG) - KRACAK



LOKASI : STA 0+800

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 4 M
CATATAN : Aspal

LOKASI : STA 0+900

KONDISI PERKERASAN : Sendang
LEBAR PERKERASAN : 4 M
CATATAN : Aspal

NO. RUAS	NAMA RUAS	DPU KABUPATEN BANYUMAS	PETUGAS SURVEY	HALAMAN
13	JL. CIBERUNG (JEMB. TONJONG) - KRACAK			5

FOTO SURVEY KONDISI JALAN TAHUN 2023

RUAS JALAN : JL. CIBERUNG (JEMB. TONJONG) - KRACAK



LOKASI : STA 1+000

KONDISI PERKERASAN : Sendang
LEBAR PERKERASAN : 4 M
CATATAN : Aspal

LOKASI : STA 1+100

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 4 M
CATATAN : Aspal

NO. RUAS	NAMA RUAS	DPU KABUPATEN BANYUMAS	PETUGAS SURVEY	HALAMAN
13	JL. CIBERUNG (JEMB. TONJONG) - KRACAK			6

FOTO SURVEY KONDISI JALAN TAHUN 2023

RUAS JALAN : JL. CIBERUNG (JEMB. TONJONG) - KRACAK



LOKASI : STA 1+200

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 4 M
CATATAN : Aspal



LOKASI : STA 1+300

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 4 M
CATATAN : Aspal

NO. RUAS	NAMA RUAS	DPU KABUPATEN BANYUMAS	PETUGAS SURVEY	HALAMAN
13	JL. CIBERUNG (JEMB. TONJONG) - KRACAK			7

FOTO SURVEY KONDISI JALAN TAHUN 2023

RUAS JALAN : JL. CIBERUNG (JEMB. TONJONG) - KRACAK



LOKASI : STA 1+400

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 3,5 M
CATATAN : Aspal



LOKASI : STA 1+500

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 3,5 M
CATATAN : Aspal

NO. RUAS	NAMA RUAS	DPU KABUPATEN BANYUMAS	PETUGAS SURVEY	HALAMAN
13	JL. CIBERUNG (JEMB. TONJONG) - KRACAK			8

FOTO SURVEY KONDISI JALAN TAHUN 2023

RUAS JALAN : JL. CIBERUNG (JEMB. TONJONG) - KRACAK



LOKASI : STA 1+600

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 3,5 M
CATATAN : Aspal

LOKASI : STA 1+700

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 3,5 M
CATATAN : Aspal

NO. RUAS	NAMA RUAS	DPU KABUPATEN BANYUMAS	PETUGAS SURVEY	HALAMAN
13	JL. CIBERUNG (JEMB. TONJONG) - KRACAK			9

FOTO SURVEY KONDISI JALAN TAHUN 2023

RUAS JALAN : JL. CIBERUNG (JEMB. TONJONG) - KRACAK



LOKASI : STA 1+800

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 3,5 M
CATATAN : Aspal

LOKASI : STA 1+900

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 3,5 M
CATATAN : Aspal

NO. RUAS	NAMA RUAS	DPU KABUPATEN BANYUMAS	PETUGAS SURVEY	HALAMAN
13	JL. CIBERUNG (JEMB. TONJONG) - KRACAK			10

FOTO SURVEY KONDISI JALAN TAHUN 2023

RUAS JALAN : JL. CIBERUNG (JEMB. TONJONG) - KRACAK



LOKASI : STA 2+000

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 3,5 M
CATATAN : Aspal



LOKASI : STA 2+100

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 3,5 M
CATATAN : Aspal

NO. RUAS	NAMA RUAS	DPU KABUPATEN BANYUMAS	PETUGAS SURVEY	HALAMAN
13	JL. CIBERUNG (JEMB. TONJONG) - KRACAK			11

FOTO SURVEY KONDISI JALAN TAHUN 2023

RUAS JALAN : JL. CIBERUNG (JEMB. TONJONG) - KRACAK



LOKASI : STA 2+200

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 3,5 M
CATATAN : Aspal




LOKASI : STA 2+300

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 3,5 M
CATATAN : Aspal

NO. RUAS	NAMA RUAS	DPU KABUPATEN BANYUMAS	PETUGAS SURVEY	HALAMAN
13	JL. CIBERUNG (JEMB. TONJONG) - KRACAK			12

FOTO SURVEY KONDISI JALAN TAHUN 2023

RUAS JALAN : JL. CIBERUNG (JEMB. TONJONG) - KRACAK



LOKASI : **STA** **2+400**

KONDISI PERKERASAN : Baik

LEBAR PERKERASAN : 3,5 M

CATATAN : Aspal

NO. RUAS	NAMA RUAS	DPU KABUPATEN BANYUMAS	PETUGAS SURVEY	HALAMAN
13	JL. CIBERUNG (JEMB. TONJONG) - KRACAK			13