

### FOTO SURVEY KONDISI JALAN TAHUN 2023

RUAS JALAN : Windujaya - Kalisalak



LOKASI : STA 0+000

KONDISI PERKERASAN : Rusak Ringan

LEBAR PERKERASAN : 6 M

CATATAN : Aspal

LOKASI : STA 0+030

KONDISI PERKERASAN : Baik

LEBAR PERKERASAN : 3 M

CATATAN : Aspal

| NO. RUAS | NAMA RUAS             | DPU KABUPATEN BANYUMAS | PETUGAS SURVEY | HALAMAN |
|----------|-----------------------|------------------------|----------------|---------|
| 198      | Windujaya - Kalisalak |                        |                | 1       |

### FOTO SURVEY KONDISI JALAN TAHUN 2023

RUAS JALAN : Windujaya - Kalisalak



LOKASI : STA 0+100

KONDISI PERKERASAN : Baik

LEBAR PERKERASAN : 3 M

CATATAN : Aspal

LOKASI : STA 0+125

KONDISI PERKERASAN : Sedang

LEBAR PERKERASAN : 3 M

CATATAN : Aspal

| NO. RUAS | NAMA RUAS             | DPU KABUPATEN BANYUMAS | PETUGAS SURVEY | HALAMAN |
|----------|-----------------------|------------------------|----------------|---------|
| 198      | Windujaya - Kalisalak |                        |                | 1       |

### FOTO SURVEY KONDISI JALAN TAHUN 2023

RUAS JALAN : Windujaya - Kalisalak



LOKASI : STA **0+145**

KONDISI PERKERASAN : Baik  
LEBAR PERKERASAN : 3,5 M  
CATATAN : Aspal



LOKASI : STA **0+200**

KONDISI PERKERASAN : Baik  
LEBAR PERKERASAN : 3,5 M  
CATATAN : Aspal

| NO. RUAS | NAMA RUAS             | DPU KABUPATEN BANYUMAS | PETUGAS SURVEY | HALAMAN |
|----------|-----------------------|------------------------|----------------|---------|
| 198      | Windujaya - Kalisalak |                        |                | 2       |

### FOTO SURVEY KONDISI JALAN TAHUN 2023

RUAS JALAN : Windujaya - Kalisalak



LOKASI : STA **0+210**

KONDISI PERKERASAN : Sedang  
LEBAR PERKERASAN : 3,5 M  
CATATAN : Aspal


LOKASI : STA **0+220**

KONDISI PERKERASAN : Baik  
LEBAR PERKERASAN : 3,5 M  
CATATAN : Aspal

| NO. RUAS | NAMA RUAS             | DPU KABUPATEN BANYUMAS | PETUGAS SURVEY | HALAMAN |
|----------|-----------------------|------------------------|----------------|---------|
| 198      | Windujaya - Kalisalak |                        |                | 2       |

### FOTO SURVEY KONDISI JALAN TAHUN 2023

RUAS JALAN : Windujaya - Kalisalak



LOKASI : STA **0+300**

KONDISI PERKERASAN : Baik  
LEBAR PERKERASAN : 3,5 M  
CATATAN : Aspal

LOKASI : STA **0+400**

KONDISI PERKERASAN : Baik  
LEBAR PERKERASAN : 3,5 M  
CATATAN : Aspal

| NO. RUAS | NAMA RUAS             | DPU KABUPATEN BANYUMAS | PETUGAS SURVEY | HALAMAN |
|----------|-----------------------|------------------------|----------------|---------|
| 198      | Windujaya - Kalisalak |                        |                | 3       |

### FOTO SURVEY KONDISI JALAN TAHUN 2023

RUAS JALAN : Windujaya - Kalisalak



LOKASI : STA **0+425**

KONDISI PERKERASAN : Rusak Ringan  
LEBAR PERKERASAN : 3,5 M  
CATATAN : Aspal

LOKASI : STA **0+440**

KONDISI PERKERASAN : Baik  
LEBAR PERKERASAN : 3,5 M  
CATATAN : Aspal

| NO. RUAS | NAMA RUAS             | DPU KABUPATEN BANYUMAS | PETUGAS SURVEY | HALAMAN |
|----------|-----------------------|------------------------|----------------|---------|
| 198      | Windujaya - Kalisalak |                        |                | 3       |

### FOTO SURVEY KONDISI JALAN TAHUN 2023

RUAS JALAN : Windujaya - Kalisalak



LOKASI : STA 0+500

KONDISI PERKERASAN : Baik  
LEBAR PERKERASAN : 3,5 M  
CATATAN : Aspal



LOKASI : STA 0+524

KONDISI PERKERASAN : Rusak Berat  
LEBAR PERKERASAN : 3,5 M  
CATATAN : Aspal

| NO. RUAS | NAMA RUAS             | DPU KABUPATEN BANYUMAS | PETUGAS SURVEY | HALAMAN |
|----------|-----------------------|------------------------|----------------|---------|
| 198      | Windujaya - Kalisalak |                        |                | 3       |

### FOTO SURVEY KONDISI JALAN TAHUN 2023

RUAS JALAN : Windujaya - Kalisalak



LOKASI : STA 0+600

KONDISI PERKERASAN : Rusak Ringan  
LEBAR PERKERASAN : 3,5 M  
CATATAN : Aspal



LOKASI : STA 0+700

KONDISI PERKERASAN : Rusak Ringan  
LEBAR PERKERASAN : 3,5 M  
CATATAN : Aspal

| NO. RUAS | NAMA RUAS             | DPU KABUPATEN BANYUMAS | PETUGAS SURVEY | HALAMAN |
|----------|-----------------------|------------------------|----------------|---------|
| 198      | Windujaya - Kalisalak |                        |                | 4       |

### FOTO SURVEY KONDISI JALAN TAHUN 2023

RUAS JALAN : Windujaya - Kalisalak



LOKASI : STA 0+800

KONDISI PERKERASAN : Rusak Berat  
LEBAR PERKERASAN : 3,5 M  
CATATAN : Aspal

LOKASI : STA 0+900

KONDISI PERKERASAN : Rusak Berat  
LEBAR PERKERASAN : 3,5 M  
CATATAN : Aspal

| NO. RUAS | NAMA RUAS             | DPU KABUPATEN BANYUMAS | PETUGAS SURVEY | HALAMAN |
|----------|-----------------------|------------------------|----------------|---------|
| 198      | Windujaya - Kalisalak |                        |                | 5       |

### FOTO SURVEY KONDISI JALAN TAHUN 2023

RUAS JALAN : Windujaya - Kalisalak



LOKASI : STA 1+000

KONDISI PERKERASAN : Rusak Berat  
LEBAR PERKERASAN : 3,5 M  
CATATAN : Aspal

LOKASI : STA 1+100

KONDISI PERKERASAN : Rusak Ringan  
LEBAR PERKERASAN : 3,5 M  
CATATAN : Aspal

| NO. RUAS | NAMA RUAS             | DPU KABUPATEN BANYUMAS | PETUGAS SURVEY | HALAMAN |
|----------|-----------------------|------------------------|----------------|---------|
| 198      | Windujaya - Kalisalak |                        |                | 6       |

### FOTO SURVEY KONDISI JALAN TAHUN 2023

RUAS JALAN : Windujaya - Kalisalak



LOKASI : STA 1+200

KONDISI PERKERASAN : Rusak Ringan  
LEBAR PERKERASAN : 3,5 M  
CATATAN : Aspal

LOKASI : STA 1+300

KONDISI PERKERASAN : Baik  
LEBAR PERKERASAN : 3,5 M  
CATATAN : Aspal

| NO. RUAS | NAMA RUAS             | DPU KABUPATEN BANYUMAS | PETUGAS SURVEY | HALAMAN |
|----------|-----------------------|------------------------|----------------|---------|
| 198      | Windujaya - Kalisalak |                        |                | 7       |

### FOTO SURVEY KONDISI JALAN TAHUN 2023

RUAS JALAN : Windujaya - Kalisalak



LOKASI : STA 1+400

KONDISI PERKERASAN : Rusak Ringan  
LEBAR PERKERASAN : 3,5 M  
CATATAN : Aspal

LOKASI : STA 1+479

KONDISI PERKERASAN : Sedang  
LEBAR PERKERASAN : 6 M  
CATATAN : Aspal

| NO. RUAS | NAMA RUAS             | DPU KABUPATEN BANYUMAS | PETUGAS SURVEY | HALAMAN |
|----------|-----------------------|------------------------|----------------|---------|
| 198      | Windujaya - Kalisalak |                        |                | 8       |