

### FOTO SURVEY KONDISI JALAN TAHUN 2023

RUAS JALAN : JL. NUSAMANGIR - SIBALUNG



LOKASI : STA 0+000

KONDISI PERKERASAN : Sedang  
LEBAR PERKERASAN : 2,5 M  
CATATAN : Aspal

LOKASI : STA 0+100

KONDISI PERKERASAN : Sedang  
LEBAR PERKERASAN : 2,5 M  
CATATAN : Aspal

| NO. RUAS | NAMA RUAS                 | DPU KABUPATEN BANYUMAS | PETUGAS SURVEY | HALAMAN |
|----------|---------------------------|------------------------|----------------|---------|
| 238      | JL. NUSAMANGIR - SIBALUNG |                        |                | 1       |

### FOTO SURVEY KONDISI JALAN TAHUN 2023

RUAS JALAN : JL. NUSAMANGIR - SIBALUNG



LOKASI : STA 0+200

KONDISI PERKERASAN : Sedang  
LEBAR PERKERASAN : 2,5 M  
CATATAN : Aspal

LOKASI : STA 0+300

KONDISI PERKERASAN : Rusak Ringan  
LEBAR PERKERASAN : 2,5 M  
CATATAN : Aspal

| NO. RUAS | NAMA RUAS                 | DPU KABUPATEN BANYUMAS | PETUGAS SURVEY | HALAMAN |
|----------|---------------------------|------------------------|----------------|---------|
| 238      | JL. NUSAMANGIR - SIBALUNG |                        |                | 2       |

### FOTO SURVEY KONDISI JALAN TAHUN 2023

RUAS JALAN : JL. NUSAMANGIR - SIBALUNG



LOKASI : STA 0+400

KONDISI PERKERASAN : Sedang  
LEBAR PERKERASAN : 2,5 M  
CATATAN : Aspal



LOKASI : STA 0+500

KONDISI PERKERASAN : Rusak Ringan  
LEBAR PERKERASAN : 3 M  
CATATAN : Beton

| NO. RUAS | NAMA RUAS                 | DPU KABUPATEN BANYUMAS | PETUGAS SURVEY | HALAMAN |
|----------|---------------------------|------------------------|----------------|---------|
| 238      | JL. NUSAMANGIR - SIBALUNG |                        |                | 3       |

### FOTO SURVEY KONDISI JALAN TAHUN 2023

RUAS JALAN : JL. NUSAMANGIR - SIBALUNG



LOKASI : STA 0+530

KONDISI PERKERASAN : Rusak Ringan  
LEBAR PERKERASAN : 3 M  
CATATAN : Aspal



LOKASI : STA 0+600

KONDISI PERKERASAN : Rusak Ringan  
LEBAR PERKERASAN : 3 M  
CATATAN : Aspal

| NO. RUAS | NAMA RUAS                 | DPU KABUPATEN BANYUMAS | PETUGAS SURVEY | HALAMAN |
|----------|---------------------------|------------------------|----------------|---------|
| 238      | JL. NUSAMANGIR - SIBALUNG |                        |                | 4       |

### FOTO SURVEY KONDISI JALAN TAHUN 2023

RUAS JALAN : JL. NUSAMANGIR - SIBALUNG



LOKASI : STA 0+700

KONDISI PERKERASAN : Rusak Berat  
LEBAR PERKERASAN : 3 M  
CATATAN : Aspal

LOKASI : STA 0+800

KONDISI PERKERASAN : Rusak Berat  
LEBAR PERKERASAN : 3 M  
CATATAN : Aspal

| NO. RUAS | NAMA RUAS                 | DPU KABUPATEN BANYUMAS | PETUGAS SURVEY | HALAMAN |
|----------|---------------------------|------------------------|----------------|---------|
| 238      | JL. NUSAMANGIR - SIBALUNG |                        |                | 5       |

### FOTO SURVEY KONDISI JALAN TAHUN 2023

RUAS JALAN : JL. NUSAMANGIR - SIBALUNG



LOKASI : STA 0+900

KONDISI PERKERASAN : Rusak Berat  
LEBAR PERKERASAN : 3 M  
CATATAN : Aspal

LOKASI : STA 1+000

KONDISI PERKERASAN : Rusak Berat  
LEBAR PERKERASAN : 3 M  
CATATAN : Aspal

| NO. RUAS | NAMA RUAS                 | DPU KABUPATEN BANYUMAS | PETUGAS SURVEY | HALAMAN |
|----------|---------------------------|------------------------|----------------|---------|
| 238      | JL. NUSAMANGIR - SIBALUNG |                        |                | 6       |

### FOTO SURVEY KONDISI JALAN TAHUN 2023

RUAS JALAN : JL. NUSAMANGIR - SIBALUNG



LOKASI : STA 1+100

KONDISI PERKERASAN : Rusak Berat  
LEBAR PERKERASAN : 3 M  
CATATAN : Aspal


LOKASI : STA 1+200

KONDISI PERKERASAN : Rusak Berat  
LEBAR PERKERASAN : 3 M  
CATATAN : Aspal

| NO. RUAS | NAMA RUAS                 | DPU KABUPATEN BANYUMAS | PETUGAS SURVEY | HALAMAN |
|----------|---------------------------|------------------------|----------------|---------|
| 238      | JL. NUSAMANGIR - SIBALUNG |                        |                | 7       |

### FOTO SURVEY KONDISI JALAN TAHUN 2023

RUAS JALAN : JL. NUSAMANGIR - SIBALUNG



LOKASI : STA 1+300

KONDISI PERKERASAN : Sedang  
LEBAR PERKERASAN : 3 M  
CATATAN : Aspal


LOKASI : STA 1+400

KONDISI PERKERASAN : Rusak Berat  
LEBAR PERKERASAN : 3 M  
CATATAN : Aspal

| NO. RUAS | NAMA RUAS                 | DPU KABUPATEN BANYUMAS | PETUGAS SURVEY | HALAMAN |
|----------|---------------------------|------------------------|----------------|---------|
| 238      | JL. NUSAMANGIR - SIBALUNG |                        |                | 8       |

### FOTO SURVEY KONDISI JALAN TAHUN 2023

RUAS JALAN : JL. NUSAMANGIR - SIBALUNG



LOKASI : STA 1+500

KONDISI PERKERASAN : Rusak Ringan  
LEBAR PERKERASAN : 3 M  
CATATAN : Aspal



LOKASI : STA 1+600

KONDISI PERKERASAN : Rusak Ringan  
LEBAR PERKERASAN : 3 M  
CATATAN : Aspal

| NO. RUAS | NAMA RUAS                 | DPU KABUPATEN BANYUMAS | PETUGAS SURVEY | HALAMAN |
|----------|---------------------------|------------------------|----------------|---------|
| 238      | JL. NUSAMANGIR - SIBALUNG |                        |                | 9       |

### FOTO SURVEY KONDISI JALAN TAHUN 2023

RUAS JALAN : JL. NUSAMANGIR - SIBALUNG



LOKASI : STA 1+700

KONDISI PERKERASAN : Rusak Ringan  
LEBAR PERKERASAN : 3 M  
CATATAN : Aspal




LOKASI : STA 1+800

KONDISI PERKERASAN : Rusak Berat  
LEBAR PERKERASAN : 3 M  
CATATAN : Aspal

| NO. RUAS | NAMA RUAS                 | DPU KABUPATEN BANYUMAS | PETUGAS SURVEY | HALAMAN |
|----------|---------------------------|------------------------|----------------|---------|
| 238      | JL. NUSAMANGIR - SIBALUNG |                        |                | 10      |

## FOTO SURVEY KONDISI JALAN TAHUN 2023

RUAS JALAN : JL. NUSAMANGIR - SIBALUNG



LOKASI : STA 1+860

KONDISI PERKERASAN : Sedang

LEBAR PERKERASAN : 3 M

CATATAN : Aspal

| NO. RUAS | NAMA RUAS                 | DPU KABUPATEN BANYUMAS | PETUGAS SURVEY | HALAMAN |
|----------|---------------------------|------------------------|----------------|---------|
| 238      | JL. NUSAMANGIR - SIBALUNG |                        |                | 11      |