

FOTO SURVEY KONDISI JALAN TAHUN 2023

RUAS JALAN : CIBANGKONG - CIHONJE



11 Nov 2023 13.28.43
7,389448S 109,056023E
Kecamatan Pekuncen
#NO RUAS 277 #STA 0+000
#Kab. Banyumas #Survey SDI dan RNI

LOKASI : STA 0+000

KONDISI PERKERASAN : Sedang

LEBAR PERKERASAN : 4 M

CATATAN : Aspal

NO. RUAS	NAMA RUAS	DPU KABUPATEN BANYUMAS	PETUGAS SURVEY	HALAMAN
277	CIBANGKONG - CIHONJE			1



11 Nov 2023 13.31.10
7,389270S 109,055042E
Kecamatan Pekuncen
#NO RUAS 277 #STA 0+100
#Kab. Banyumas #Survey SDI dan RNI

LOKASI : STA 0+100

KONDISI PERKERASAN : Rusak Ringan

LEBAR PERKERASAN : 4 M

CATATAN : Aspal

FOTO SURVEY KONDISI JALAN TAHUN 2023

RUAS JALAN : CIBANGKONG - CIHONJE



11 Nov 2023 13.32.22
7,389193S 109,054855E
Kecamatan Pekuncen
#NO RUAS 277 #STA 0+120
#Kab. Banyumas #Survey SDI dan RNI

LOKASI : STA 0+120

KONDISI PERKERASAN : Sedang

LEBAR PERKERASAN : 4 M

CATATAN : Aspal

NO. RUAS	NAMA RUAS	DPU KABUPATEN BANYUMAS	PETUGAS SURVEY	HALAMAN
277	CIBANGKONG - CIHONJE			2



11 Nov 2023 13.33.00
7,389038S 109,054222E
Kecamatan Pekuncen
#NO RUAS 277 #STA 0+200
#Kab. Banyumas #Survey SDI dan RNI

LOKASI : STA 0+200

KONDISI PERKERASAN : Baik

LEBAR PERKERASAN : 4 M

CATATAN : Aspal

FOTO SURVEY KONDISI JALAN TAHUN 2023
RUAS JALAN : CIBANGKONG - CIHONJE



LOKASI :	STA	0+300	LOKASI :	STA	0+400
KONDISI PERKERASAN	:	Sedang	KONDISI PERKERASAN	:	Sedang
LEBAR PERKERASAN	:	4 M	LEBAR PERKERASAN	:	4 M
CATATAN	:	Aspal	CATATAN	:	Aspal
NO. RUAS 277	NAMA RUAS CIBANGKONG - CIHONJE	DPU KABUPATEN BANYUMAS	PETUGAS SURVEY	HALAMAN 3	

FOTO SURVEY KONDISI JALAN TAHUN 2023
RUAS JALAN : CIBANGKONG - CIHONJE



LOKASI :	STA	0+500	LOKASI :	STA	0+600
KONDISI PERKERASAN	:	Baik	KONDISI PERKERASAN	:	Sedang
LEBAR PERKERASAN	:	4 M	LEBAR PERKERASAN	:	4 M
CATATAN	:	Aspal	CATATAN	:	Aspal
NO. RUAS 277	NAMA RUAS CIBANGKONG - CIHONJE	DPU KABUPATEN BANYUMAS	PETUGAS SURVEY	HALAMAN 4	

FOTO SURVEY KONDISI JALAN TAHUN 2023

RUAS JALAN : CIBANGKONG - CIHONJE



11 Nov 2023 13.37.12
7,388590S 109,049783E
Kecamatan Pekuncen
#NO RUAS 277 #STA 0+700
#Kab. Banyumas #Survey SDI dan RNI



11 Nov 2023 13.37.54
7,389193S 109,049063E
Kecamatan Pekuncen
#NO RUAS 277 #STA 0+800
#Kab. Banyumas #Survey SDI dan RNI

LOKASI : STA 0+700

KONDISI PERKERASAN : Sedang

LEBAR PERKERASAN : 4 M

CATATAN : Aspal

LOKASI : STA 0+800

KONDISI PERKERASAN : Rusak Ringan

LEBAR PERKERASAN : 4 M

CATATAN : Aspal

NO. RUAS	NAMA RUAS	DPU KABUPATEN BANYUMAS	PETUGAS SURVEY	HALAMAN
277	CIBANGKONG - CIHONJE			5

FOTO SURVEY KONDISI JALAN TAHUN 2023

RUAS JALAN : CIBANGKONG - CIHONJE



11 Nov 2023 13.38.39
7,389698S 109,048548E
Kecamatan Pekuncen
#NO RUAS 277 #STA 0+900
#Kab. Banyumas #Survey SDI dan RNI



11 Nov 2023 13.41.27
7,390295S 109,047718E
Kecamatan Pekuncen
#NO RUAS 277 #STA 1+000
#Kab. Banyumas #Survey SDI dan RNI

LOKASI : STA 0+900

KONDISI PERKERASAN : Rusak Ringan

LEBAR PERKERASAN : 4 M

CATATAN : Aspal

LOKASI : STA 1+000

KONDISI PERKERASAN : Sedang

LEBAR PERKERASAN : 4 M

CATATAN : Aspal

NO. RUAS	NAMA RUAS	DPU KABUPATEN BANYUMAS	PETUGAS SURVEY	HALAMAN
277	CIBANGKONG - CIHONJE			6

FOTO SURVEY KONDISI JALAN TAHUN 2023

RUAS JALAN : CIBANGKONG - CIHONJE



11 Nov 2023 13.42.17
7,391017S 109,047092E
Kecamatan Pekuncen
#NO RUAS 277 #STA 1+100
#Kab. Banyumas #Survey SDI dan RNI

LOKASI :
STA
1+100

KONDISI PERKERASAN :
Sedang

LEBAR PERKERASAN :
4 M

CATATAN :
Aspal

NO. RUAS	NAMA RUAS	DPU KABUPATEN BANYUMAS	PETUGAS SURVEY	HALAMAN
277	CIBANGKONG - CIHONJE			7



11 Nov 2023 13.43.12
7,391697S 109,046797E
Kecamatan Pekuncen
#NO RUAS 277 #STA 1+200
#Kab. Banyumas #Survey SDI dan RNI

LOKASI :
STA
1+200

KONDISI PERKERASAN :
Baik

LEBAR PERKERASAN :
4 M

CATATAN :
Aspal

NO. RUAS	NAMA RUAS	DPU KABUPATEN BANYUMAS	PETUGAS SURVEY	HALAMAN
277	CIBANGKONG - CIHONJE			7

FOTO SURVEY KONDISI JALAN TAHUN 2023

RUAS JALAN : CIBANGKONG - CIHONJE



11 Nov 2023 13.44.00
7,392047S 109,045938E
Kecamatan Pekuncen
#NO RUAS 277 #STA 1+300
#Kab. Banyumas #Survey SDI dan RNI

LOKASI :
STA
1+300

KONDISI PERKERASAN :
Baik

LEBAR PERKERASAN :
4 M

CATATAN :
Aspal

NO. RUAS	NAMA RUAS	DPU KABUPATEN BANYUMAS	PETUGAS SURVEY	HALAMAN
277	CIBANGKONG - CIHONJE			8



11 Nov 2023 13.44.45
7,392287S 109,045193E
Kecamatan Pekuncen
#NO RUAS 277 #STA 1+400
#Kab. Banyumas #Survey SDI dan RNI

LOKASI :
STA
1+400

KONDISI PERKERASAN :
Baik

LEBAR PERKERASAN :
4 M

CATATAN :
Aspal

NO. RUAS	NAMA RUAS	DPU KABUPATEN BANYUMAS	PETUGAS SURVEY	HALAMAN
277	CIBANGKONG - CIHONJE			8

FOTO SURVEY KONDISI JALAN TAHUN 2023

RUAS JALAN : CIBANGKONG - CIHONJE



11 Nov 2023 13.45.40
7,392635S 109,044080E
Kecamatan Pekuncen
#NO RUAS 277 #STA 1+500
#Kab. Banyumas #Survey SDI dan RNI



11 Nov 2023 13.46.15
7,392842S 109,043243E
Kecamatan Pekuncen
#NO RUAS 277 #STA 1+600
#Kab. Banyumas #Survey SDI dan RNI

LOKASI : STA 1+500

KONDISI PERKERASAN : Sedang

LEBAR PERKERASAN : 4 M

CATATAN : Aspal

LOKASI : STA 1+600

KONDISI PERKERASAN : Baik

LEBAR PERKERASAN : 4 M

CATATAN : Aspal

NO. RUAS	NAMA RUAS	DPU KABUPATEN BANYUMAS	PETUGAS SURVEY	HALAMAN
277	CIBANGKONG - CIHONJE			9

FOTO SURVEY KONDISI JALAN TAHUN 2023

RUAS JALAN : CIBANGKONG - CIHONJE



11 Nov 2023 13.47.05
7,393585S 109,042692E
Kecamatan Pekuncen
#NO RUAS 277 #STA 1+700
#Kab. Banyumas #Survey SDI dan RNI



11 Nov 2023 13.47.44
7,394113S 109,042202E
Kecamatan Pekuncen
#NO RUAS 277 #STA 1+800
#Kab. Banyumas #Survey SDI dan RNI

LOKASI : STA 1+700

KONDISI PERKERASAN : Baik

LEBAR PERKERASAN : 4 M

CATATAN : Aspal

LOKASI : STA 1+800

KONDISI PERKERASAN : Baik

LEBAR PERKERASAN : 4 M

CATATAN : Aspal

NO. RUAS	NAMA RUAS	DPU KABUPATEN BANYUMAS	PETUGAS SURVEY	HALAMAN
277	CIBANGKONG - CIHONJE			10

FOTO SURVEY KONDISI JALAN TAHUN 2023

RUAS JALAN : CIBANGKONG - CIHONJE



11 Nov 2023 13.48.37
7,394328S 109,041937E
Kecamatan Pekuncen
#NO RUAS 277 #STA 1+820
#Kab. Banyumas #Survey SDI dan RNI



11 Nov 2023 13.49.00
7,394395S 109,041857E
Kecamatan Pekuncen
#NO RUAS 277 #STA 1+830
#Kab. Banyumas #Survey SDI dan RNI

LOKASI : STA 1+820

KONDISI PERKERASAN : Rusak Ringan

LEBAR PERKERASAN : 4 M

CATATAN : Aspal

LOKASI : STA 1+830

KONDISI PERKERASAN : Baik

LEBAR PERKERASAN : 4 M

CATATAN : Aspal

NO. RUAS	NAMA RUAS	DPU KABUPATEN BANYUMAS	PETUGAS SURVEY	HALAMAN
277	CIBANGKONG - CIHONJE			11

FOTO SURVEY KONDISI JALAN TAHUN 2023

RUAS JALAN : CIBANGKONG - CIHONJE



11 Nov 2023 13.49.41
7,394653S 109,041298E
Kecamatan Pekuncen
#NO RUAS 277 #STA 1+900
#Kab. Banyumas #Survey SDI dan RNI



11 Nov 2023 13.51.23
7,394965S 109,040566E
Kecamatan Pekuncen
#NO RUAS 277 #STA 2+000
#Kab. Banyumas #Survey SDI dan RNI

LOKASI : STA 1+900

KONDISI PERKERASAN : Sedang

LEBAR PERKERASAN : 4 M

CATATAN : Aspal

LOKASI : STA 2+000

KONDISI PERKERASAN : Baik

LEBAR PERKERASAN : 4 M

CATATAN : Aspal

NO. RUAS	NAMA RUAS	DPU KABUPATEN BANYUMAS	PETUGAS SURVEY	HALAMAN
277	CIBANGKONG - CIHONJE			12

FOTO SURVEY KONDISI JALAN TAHUN 2023

RUAS JALAN : CIBANGKONG - CIHONJE



11 Nov 2023 13.51.55
7,395267S 109,039678E
Kecamatan Pekuncen
#NO RUAS 277 #STA 2+100
#Kab. Banyumas #Survey SDI dan RNI

LOKASI : STA 2+100

KONDISI PERKERASAN : Rusak Ringan

LEBAR PERKERASAN : 4 M

CATATAN : Aspal



11 Nov 2023 13.52.31
7,395337S 109,039490E
Kecamatan Pekuncen
#NO RUAS 277 #STA 2+110
#Kab. Banyumas #Survey SDI dan RNI

LOKASI : STA 2+110

KONDISI PERKERASAN : Baik

LEBAR PERKERASAN : 4 M

CATATAN : Aspal

NO. RUAS	NAMA RUAS	DPU KABUPATEN BANYUMAS	PETUGAS SURVEY	HALAMAN
277	CIBANGKONG - CIHONJE			13

FOTO SURVEY KONDISI JALAN TAHUN 2023

RUAS JALAN : CIBANGKONG - CIHONJE



11 Nov 2023 13.53.00
7,395552S 109,038653E
Kecamatan Pekuncen
#NO RUAS 277 #STA 2+200
#Kab. Banyumas #Survey SDI dan RNI

LOKASI : STA 2+200

KONDISI PERKERASAN : Baik

LEBAR PERKERASAN : 4 M

CATATAN : Aspal



11 Nov 2023 13.53.38
7,396030S 109,038113E
Kecamatan Pekuncen
#NO RUAS 277 #STA 2+300
#Kab. Banyumas #Survey SDI dan RNI

LOKASI : STA 2+300

KONDISI PERKERASAN : Baik

LEBAR PERKERASAN : 4 M

CATATAN : Aspal

NO. RUAS	NAMA RUAS	DPU KABUPATEN BANYUMAS	PETUGAS SURVEY	HALAMAN
277	CIBANGKONG - CIHONJE			14

FOTO SURVEY KONDISI JALAN TAHUN 2023				
RUAS JALAN : CIBANGKONG - CIHONJE				
 11 Nov 2023 13.54.12 7,396740S 109,037587E Kecamatan Pekuncen #NO RUAS 277 #STA 2+400 #Kab. Banyumas #Survey SDI dan RNI  11 Nov 2023 13.54.55 7,397215S 109,036848E Kecamatan Pekuncen #NO RUAS 277 #STA 2+500 #Kab. Banyumas #Survey SDI dan RNI				
LOKASI :	STA	2+400	LOKASI :	STA 2+500
KONDISI PERKERASAN	:	Baik	KONDISI PERKERASAN	: Sedang
LEBAR PERKERASAN	:	4 M	LEBAR PERKERASAN	: 4 M
CATATAN	:	Aspal	CATATAN	: Aspal
NO. RUAS	NAMA RUAS	DPU KABUPATEN BANYUMAS	PETUGAS SURVEY	HALAMAN
277	CIBANGKONG - CIHONJE			15

FOTO SURVEY KONDISI JALAN TAHUN 2023				
RUAS JALAN : CIBANGKONG - CIHONJE				
 11 Nov 2023 13.55.46 7,397397S 109,036263E Kecamatan Pekuncen #NO RUAS 277 #STA 2+540 #Kab. Banyumas #Survey SDI dan RNI  11 Nov 2023 13.56.16 7,397625S 109,035862E Kecamatan Pekuncen #NO RUAS 277 #STA 2+600 #Kab. Banyumas #Survey SDI dan RNI				
LOKASI :	STA	2+540	LOKASI :	STA 2+600
KONDISI PERKERASAN	:	Baik	KONDISI PERKERASAN	: Baik
LEBAR PERKERASAN	:	4 M	LEBAR PERKERASAN	: 4 M
CATATAN	:	Aspal	CATATAN	: Aspal
NO. RUAS	NAMA RUAS	DPU KABUPATEN BANYUMAS	PETUGAS SURVEY	HALAMAN
277	CIBANGKONG - CIHONJE			16

FOTO SURVEY KONDISI JALAN TAHUN 2023

RUAS JALAN : CIBANGKONG - CIHONJE



LOKASI : STA 2+700

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 4 M
CATATAN : Aspal



LOKASI : STA 2+800

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 4 M
CATATAN : Aspal

NO. RUAS	NAMA RUAS	DPU KABUPATEN BANYUMAS	PETUGAS SURVEY	HALAMAN
277	CIBANGKONG - CIHONJE			17

FOTO SURVEY KONDISI JALAN TAHUN 2023

RUAS JALAN : CIBANGKONG - CIHONJE



LOKASI : STA 2+900

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 4 M
CATATAN : Aspal



LOKASI : STA 3+000

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 4 M
CATATAN : Aspal

NO. RUAS	NAMA RUAS	DPU KABUPATEN BANYUMAS	PETUGAS SURVEY	HALAMAN
277	CIBANGKONG - CIHONJE			18

FOTO SURVEY KONDISI JALAN TAHUN 2023

RUAS JALAN : CIBANGKONG - CIHONJE



LOKASI : STA 3+100

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 4 M
CATATAN : Aspal

LOKASI : STA 3+120

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 4 M
CATATAN : Aspal

NO. RUAS	NAMA RUAS	DPU KABUPATEN BANYUMAS	PETUGAS SURVEY	HALAMAN
277	CIBANGKONG - CIHONJE			19

FOTO SURVEY KONDISI JALAN TAHUN 2023

RUAS JALAN : CIBANGKONG - CIHONJE



LOKASI : STA 3+200

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 4 M
CATATAN : Aspal

LOKASI : STA 3+230

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 4 M
CATATAN : Aspal

NO. RUAS	NAMA RUAS	DPU KABUPATEN BANYUMAS	PETUGAS SURVEY	HALAMAN
277	CIBANGKONG - CIHONJE			20

FOTO SURVEY KONDISI JALAN TAHUN 2023

RUAS JALAN : CIBANGKONG - CIHONJE



11 Nov 2023 14.05.24
7,396542S 109,029311E
Kecamatan Gumelar
#NO RUAS 277 #STA 3+300
#Kab. Banyumas #Survey SDI dan RNI



11 Nov 2023 14.05.58
7,396395S 109,028822E
Kecamatan Gumelar
#NO RUAS 277 #STA 3+400
#Kab. Banyumas #Survey SDI dan RNI

LOKASI : STA 3+300

KONDISI PERKERASAN : Baik

LEBAR PERKERASAN : 4 M

CATATAN : Aspal

LOKASI : STA 3+400

KONDISI PERKERASAN : Baik

LEBAR PERKERASAN : 4 M

CATATAN : Aspal

NO. RUAS	NAMA RUAS	DPU KABUPATEN BANYUMAS	PETUGAS SURVEY	HALAMAN
277	CIBANGKONG - CIHONJE			21

FOTO SURVEY KONDISI JALAN TAHUN 2023

RUAS JALAN : CIBANGKONG - CIHONJE



11 Nov 2023 14.07.03
7,396535S 109,027594E
Kecamatan Gumelar
#NO RUAS 277 #STA 3+500
#Kab. Banyumas #Survey SDI dan RNI



11 Nov 2023 14.07.46
7,396508S 109,026648E
Kecamatan Gumelar
#NO RUAS 277 #STA 3+600
#Kab. Banyumas #Survey SDI dan RNI

LOKASI : STA 3+500

KONDISI PERKERASAN : Sedang

LEBAR PERKERASAN : 4 M

CATATAN : Aspal

LOKASI : STA 3+600

KONDISI PERKERASAN : Baik

LEBAR PERKERASAN : 4 M

CATATAN : Aspal

NO. RUAS	NAMA RUAS	DPU KABUPATEN BANYUMAS	PETUGAS SURVEY	HALAMAN
277	CIBANGKONG - CIHONJE			22

FOTO SURVEY KONDISI JALAN TAHUN 2023

RUAS JALAN : CIBANGKONG - CIHONJE



11 Nov 2023 14.08.33
7,396570S 109,025987E
Kecamatan Gumelar
#NO RUAS 277 #STA 3+700
#Kab. Banyumas #Survey SDI dan RNI



11 Nov 2023 14.09.15
7,396458S 109,024913E
Kecamatan Gumelar
#NO RUAS 277 #STA 3+800
#Kab. Banyumas #Survey SDI dan RNI

LOKASI : STA 3+700

KONDISI PERKERASAN : Sedang

LEBAR PERKERASAN : 4 M

CATATAN : Aspal

LOKASI : STA 3+800

KONDISI PERKERASAN : Sedang

LEBAR PERKERASAN : 4 M

CATATAN : Aspal

NO. RUAS	NAMA RUAS	DPU KABUPATEN BANYUMAS	PETUGAS SURVEY	HALAMAN
277	CIBANGKONG - CIHONJE			23

FOTO SURVEY KONDISI JALAN TAHUN 2023

RUAS JALAN : CIBANGKONG - CIHONJE



11 Nov 2023 14.10.05
7,396302S 109,024063E
Kecamatan Gumelar
#NO RUAS 277 #STA 3+900
#Kab. Banyumas #Survey SDI dan RNI



11 Nov 2023 14.12.35
7,395417S 109,024188E
Kecamatan Gumelar
#NO RUAS 277 #STA 4+000
#Kab. Banyumas #Survey SDI dan RNI

LOKASI : STA 3+900

KONDISI PERKERASAN : Baik

LEBAR PERKERASAN : 4 M

CATATAN : Aspal

LOKASI : STA 4+000

KONDISI PERKERASAN : Baik

LEBAR PERKERASAN : 4 M

CATATAN : Aspal

NO. RUAS	NAMA RUAS	DPU KABUPATEN BANYUMAS	PETUGAS SURVEY	HALAMAN
277	CIBANGKONG - CIHONJE			24

FOTO SURVEY KONDISI JALAN TAHUN 2023

RUAS JALAN : CIBANGKONG - CIHONJE



11 Nov 2023 14.13.24
7,394420S 109,024187E
Kecamatan Gumelar
#NO RUAS 277 #STA 4+100
#Kab. Banyumas #Survey SDI dan RNI



11 Nov 2023 14.13.59
7,393900S 109,024118E
Kecamatan Gumelar
#NO RUAS 277 #STA 4+200
#Kab. Banyumas #Survey SDI dan RNI

LOKASI : STA 4+100

KONDISI PERKERASAN : Baik

LEBAR PERKERASAN : 4 M

CATATAN : Aspal

LOKASI : STA 4+200

KONDISI PERKERASAN : Baik

LEBAR PERKERASAN : 4 M

CATATAN : Aspal

NO. RUAS	NAMA RUAS	DPU KABUPATEN BANYUMAS	PETUGAS SURVEY	HALAMAN
277	CIBANGKONG - CIHONJE			25

FOTO SURVEY KONDISI JALAN TAHUN 2023

RUAS JALAN : CIBANGKONG - CIHONJE



11 Nov 2023 14.14.43
7,393607S 109,023275E
Kecamatan Gumelar
#NO RUAS 277 #STA 4+300
#Kab. Banyumas #Survey SDI dan RNI



11 Nov 2023 14.15.27
7,392830S 109,023242E
Kecamatan Gumelar
#NO RUAS 277 #STA 4+400
#Kab. Banyumas #Survey SDI dan RNI

LOKASI : STA 4+300

KONDISI PERKERASAN : Baik

LEBAR PERKERASAN : 4 M

CATATAN : Aspal

LOKASI : STA 4+400

KONDISI PERKERASAN : Baik

LEBAR PERKERASAN : 4 M

CATATAN : Aspal

NO. RUAS	NAMA RUAS	DPU KABUPATEN BANYUMAS	PETUGAS SURVEY	HALAMAN
277	CIBANGKONG - CIHONJE			26

FOTO SURVEY KONDISI JALAN TAHUN 2023

RUAS JALAN : CIBANGKONG - CIHONJE



11 Nov 2023 14.16.16
7,391977S 109,023012E
Kecamatan Gumelar
#NO RUAS 277 #STA 4+500
#Kab. Banyumas #Survey SDI dan RNI



11 Nov 2023 14.17.13
7,391070S 109,023233E
Kecamatan Gumelar
#NO RUAS 277 #STA 4+600
#Kab. Banyumas #Survey SDI dan RNI

LOKASI : STA 4+500

KONDISI PERKERASAN : Baik

LEBAR PERKERASAN : 4 M

CATATAN : Aspal

LOKASI : STA 4+600

KONDISI PERKERASAN : Baik

LEBAR PERKERASAN : 4 M

CATATAN : Aspal

NO. RUAS	NAMA RUAS	DPU KABUPATEN BANYUMAS	PETUGAS SURVEY	HALAMAN
277	CIBANGKONG - CIHONJE			27

FOTO SURVEY KONDISI JALAN TAHUN 2023

RUAS JALAN : CIBANGKONG - CIHONJE



11 Nov 2023 14.17.56
7,390255S 109,022932E
Kecamatan Gumelar
#NO RUAS 277 #STA 4+700
#Kab. Banyumas #Survey SDI dan RNI



11 Nov 2023 14.18.34
7,389845S 109,023263E
Kecamatan Gumelar
#NO RUAS 277 #STA 4+800
#Kab. Banyumas #Survey SDI dan RNI

LOKASI : STA 4+700

KONDISI PERKERASAN : Baik

LEBAR PERKERASAN : 4 M

CATATAN : Aspal

LOKASI : STA 4+800

KONDISI PERKERASAN : Baik

LEBAR PERKERASAN : 4 M

CATATAN : Aspal

NO. RUAS	NAMA RUAS	DPU KABUPATEN BANYUMAS	PETUGAS SURVEY	HALAMAN
277	CIBANGKONG - CIHONJE			28

FOTO SURVEY KONDISI JALAN TAHUN 2023

RUAS JALAN : CIBANGKONG - CIHONJE



11 Nov 2023 14.19.14
7,389070S 109,023243E
Kecamatan Gumelar
#NO RUAS 277 #STA 4+900
#Kab. Banyumas #Survey SDI dan RNI

LOKASI : STA 4+900

KONDISI PERKERASAN : Baik

LEBAR PERKERASAN : 4 M

CATATAN : Aspal



11 Nov 2023 14.21.29
7,388062S 109,023280E
Kecamatan Gumelar
#NO RUAS 277 #STA 5+000
#Kab. Banyumas #Survey SDI dan RNI

LOKASI : STA 5+000

KONDISI PERKERASAN : Rusak Berat

LEBAR PERKERASAN : 4 M

CATATAN : Aspal

NO. RUAS	NAMA RUAS	DPU KABUPATEN BANYUMAS	PETUGAS SURVEY	HALAMAN
277	CIBANGKONG - CIHONJE			29

FOTO SURVEY KONDISI JALAN TAHUN 2023

RUAS JALAN : CIBANGKONG - CIHONJE



11 Nov 2023 14.24.41
7,386538S 109,023135E
Kecamatan Gumelar
#NO RUAS 277 #STA 5+050
#Kab. Banyumas #Survey SDI dan RNI

LOKASI : STA 5+050

KONDISI PERKERASAN : Baik

LEBAR PERKERASAN : 4 M

CATATAN : Aspal



11 Nov 2023 14.22.32
7,386988S 109,023535E
Kecamatan Gumelar
#NO RUAS 277 #STA 5+100
#Kab. Banyumas #Survey SDI dan RNI

LOKASI : STA 5+100

KONDISI PERKERASAN : Baik

LEBAR PERKERASAN : 4 M

CATATAN : Aspal

NO. RUAS	NAMA RUAS	DPU KABUPATEN BANYUMAS	PETUGAS SURVEY	HALAMAN
277	CIBANGKONG - CIHONJE			30

FOTO SURVEY KONDISI JALAN TAHUN 2023

RUAS JALAN : CIBANGKONG - CIHONJE



11 Nov 2023 14.25.40
7,386280S 109,023225E
Kecamatan Gumelar
#NO RUAS 277 #STA 5+200
#Kab. Banyumas #Survey SDI dan RNI

LOKASI : STA 5+200

KONDISI PERKERASAN : Baik

LEBAR PERKERASAN : 4 M

CATATAN : Aspal



11 Nov 2023 14.26.30
7,384957S 109,022892E
Kecamatan Gumelar
#NO RUAS 277 #STA 5+300
#Kab. Banyumas #Survey SDI dan RNI

LOKASI : STA 5+300

KONDISI PERKERASAN : Baik

LEBAR PERKERASAN : 4 M

CATATAN : Aspal

NO. RUAS	NAMA RUAS	DPU KABUPATEN BANYUMAS	PETUGAS SURVEY	HALAMAN
277	CIBANGKONG - CIHONJE			31

FOTO SURVEY KONDISI JALAN TAHUN 2023

RUAS JALAN : CIBANGKONG - CIHONJE



11 Nov 2023 14.27.10
7,384175S 109,023063E
Kecamatan Gumelar
#NO RUAS 277 #STA 5+400
#Kab. Banyumas #Survey SDI dan RNI

LOKASI : STA 5+400

KONDISI PERKERASAN : Baik

LEBAR PERKERASAN : 4 M

CATATAN : Aspal



11 Nov 2023 14.27.51
7,383312S 109,023155E
Kecamatan Gumelar
#NO RUAS 277 #STA 5+500
#Kab. Banyumas #Survey SDI dan RNI

LOKASI : STA 5+500

KONDISI PERKERASAN : Sedang

LEBAR PERKERASAN : 4 M

CATATAN : Aspal

NO. RUAS	NAMA RUAS	DPU KABUPATEN BANYUMAS	PETUGAS SURVEY	HALAMAN
277	CIBANGKONG - CIHONJE			32

FOTO SURVEY KONDISI JALAN TAHUN 2023

RUAS JALAN : CIBANGKONG - CIHONJE



11 Nov 2023 14.28.29
7,382390S 109,023193E
Kecamatan Gumelar
#NO RUAS 277 #STA 5+600
#Kab. Banyumas #Survey SDI dan RNI



11 Nov 2023 14.29.15
7,381638S 109,023275E
Kecamatan Gumelar
#NO RUAS 277 #STA 5+700
#Kab. Banyumas #Survey SDI dan RNI

LOKASI : STA 5+600

KONDISI PERKERASAN : Baik

LEBAR PERKERASAN : 4 M

CATATAN : Aspal

LOKASI : STA 5+700

KONDISI PERKERASAN : Baik

LEBAR PERKERASAN : 4 M

CATATAN : Aspal

NO. RUAS	NAMA RUAS	DPU KABUPATEN BANYUMAS	PETUGAS SURVEY	HALAMAN
277	CIBANGKONG - CIHONJE			33

FOTO SURVEY KONDISI JALAN TAHUN 2023

RUAS JALAN : CIBANGKONG - CIHONJE



11 Nov 2023 14.29.51
7,380793S 109,023030E
Kecamatan Gumelar
#NO RUAS 277 #STA 5+800
#Kab. Banyumas #Survey SDI dan RNI



11 Nov 2023 14.30.27
7,379802S 109,023022E
Kecamatan Gumelar
#NO RUAS 277 #STA 5+900
#Kab. Banyumas #Survey SDI dan RNI

LOKASI : STA 5+800

KONDISI PERKERASAN : Sedang

LEBAR PERKERASAN : 4 M

CATATAN : Aspal

LOKASI : STA 5+900

KONDISI PERKERASAN : Sedang

LEBAR PERKERASAN : 4 M

CATATAN : Aspal

NO. RUAS	NAMA RUAS	DPU KABUPATEN BANYUMAS	PETUGAS SURVEY	HALAMAN
277	CIBANGKONG - CIHONJE			34

FOTO SURVEY KONDISI JALAN TAHUN 2023

RUAS JALAN : CIBANGKONG - CIHONJE



11 Nov 2023 14.32.32
7,378748S 109,023062E
Kecamatan Gumelar
#NO RUAS 277 #STA 6+000
#Kab. Banyumas #Survey SDI dan RNI



11 Nov 2023 14.32.59
7,378627S 109,023060E
Kecamatan Gumelar
#NO RUAS 277 #STA 6+010
#Kab. Banyumas #Survey SDI dan RNI

LOKASI : STA 6+000

KONDISI PERKERASAN : Rusak Ringan

LEBAR PERKERASAN : 3 M

CATATAN : Aspal

LOKASI : STA 6+010

KONDISI PERKERASAN : Sedang

LEBAR PERKERASAN : 3 M

CATATAN : Aspal

NO. RUAS	NAMA RUAS	DPU KABUPATEN BANYUMAS	PETUGAS SURVEY	HALAMAN
277	CIBANGKONG - CIHONJE			35

FOTO SURVEY KONDISI JALAN TAHUN 2023

RUAS JALAN : CIBANGKONG - CIHONJE



11 Nov 2023 14.34.10
7,378258S 109,023022E
Kecamatan Gumelar
#NO RUAS 277 #STA 6+100
#Kab. Banyumas #Survey SDI dan RNI



11 Nov 2023 14.34.58
7,377342S 109,022955E
Kecamatan Gumelar
#NO RUAS 277 #STA 6+200
#Kab. Banyumas #Survey SDI dan RNI

LOKASI : STA 6+100

KONDISI PERKERASAN : Baik

LEBAR PERKERASAN : 3 M

CATATAN : Aspal

LOKASI : STA 6+200

KONDISI PERKERASAN : Sedang

LEBAR PERKERASAN : 3 M

CATATAN : Aspal

NO. RUAS	NAMA RUAS	DPU KABUPATEN BANYUMAS	PETUGAS SURVEY	HALAMAN
277	CIBANGKONG - CIHONJE			36

FOTO SURVEY KONDISI JALAN TAHUN 2023				
RUAS JALAN : CIBANGKONG - CIHONJE				
 11 Nov 2023 14.35.59 7,376880S 109,022087E Kecamatan Gumelar #NO RUAS 277 #STA 6+300 #Kab. Banyumas #Survey SDI dan RNI  11 Nov 2023 14.36.40 7,376553S 109,021203E Kecamatan Gumelar #NO RUAS 277 #STA 6+400 #Kab. Banyumas #Survey SDI dan RNI				
LOKASI :	STA	6+300	LOKASI :	STA 6+400
KONDISI PERKERASAN	:	Sedang	KONDISI PERKERASAN	: Sedang
LEBAR PERKERASAN	:	3 M	LEBAR PERKERASAN	: 3 M
CATATAN	:	Aspal	CATATAN	: Aspal
NO. RUAS	NAMA RUAS	DPU KABUPATEN BANYUMAS	PETUGAS SURVEY	HALAMAN
277	CIBANGKONG - CIHONJE			37

FOTO SURVEY KONDISI JALAN TAHUN 2023				
RUAS JALAN : CIBANGKONG - CIHONJE				
 11 Nov 2023 14.37.21 7,376748S 109,020378E Kecamatan Gumelar #NO RUAS 277 #STA 6+500 #Kab. Banyumas #Survey SDI dan RNI  11 Nov 2023 14.37.56 7,377005S 109,019787E Kecamatan Gumelar #NO RUAS 277 #STA 6+600 #Kab. Banyumas #Survey SDI dan RNI				
LOKASI :	STA	6+500	LOKASI :	STA 6+600
KONDISI PERKERASAN	:	Baik	KONDISI PERKERASAN	: Baik
LEBAR PERKERASAN	:	3 M	LEBAR PERKERASAN	: 3 M
CATATAN	:	Aspal	CATATAN	: Aspal
NO. RUAS	NAMA RUAS	DPU KABUPATEN BANYUMAS	PETUGAS SURVEY	HALAMAN
277	CIBANGKONG - CIHONJE			38

FOTO SURVEY KONDISI JALAN TAHUN 2023

RUAS JALAN : CIBANGKONG - CIHONJE



LOKASI :	STA	6+700	LOKASI :	STA	6+800
KONDISI PERKERASAN	:	Baik	KONDISI PERKERASAN	:	Baik
LEBAR PERKERASAN	:	3 M	LEBAR PERKERASAN	:	3 M
CATATAN	:	Aspal	CATATAN	:	Aspal
NO. RUAS	NAMA RUAS	DPU KABUPATEN BANYUMAS	PETUGAS SURVEY	HALAMAN	
277	CIBANGKONG - CIHONJE			39	

FOTO SURVEY KONDISI JALAN TAHUN 2023

RUAS JALAN : CIBANGKONG - CIHONJE



LOKASI :	STA	6+900	LOKASI :	STA	7+000
KONDISI PERKERASAN	:	Baik	KONDISI PERKERASAN	:	Sedang
LEBAR PERKERASAN	:	3 M	LEBAR PERKERASAN	:	3 M
CATATAN	:	Aspal	CATATAN	:	Aspal
NO. RUAS	NAMA RUAS	DPU KABUPATEN BANYUMAS	PETUGAS SURVEY	HALAMAN	
277	CIBANGKONG - CIHONJE			40	

FOTO SURVEY KONDISI JALAN TAHUN 2023

RUAS JALAN : CIBANGKONG - CIHONJE



LOKASI : STA 7+100

KONDISI PERKERASAN : Sedang

LEBAR PERKERASAN : 3 M

CATATAN : Aspal



LOKASI : STA 7+200

KONDISI PERKERASAN : Sedang

LEBAR PERKERASAN : 3 M

CATATAN : Aspal

NO. RUAS	NAMA RUAS	DPU KABUPATEN BANYUMAS	PETUGAS SURVEY	HALAMAN
277	CIBANGKONG - CIHONJE			41

FOTO SURVEY KONDISI JALAN TAHUN 2023

RUAS JALAN : CIBANGKONG - CIHONJE



LOKASI : STA 7+300

KONDISI PERKERASAN : Sedang

LEBAR PERKERASAN : 3 M

CATATAN : Aspal



LOKASI : STA 7+400

KONDISI PERKERASAN : Sedang

LEBAR PERKERASAN : 3 M

CATATAN : Aspal

NO. RUAS	NAMA RUAS	DPU KABUPATEN BANYUMAS	PETUGAS SURVEY	HALAMAN
277	CIBANGKONG - CIHONJE			42

FOTO SURVEY KONDISI JALAN TAHUN 2023

RUAS JALAN : CIBANGKONG - CIHONJE



11 Nov 2023 14.46.03
7,377608S 109,013167E
Kecamatan Gumelar
#NO RUAS 277 #STA 7+440
#Kab. Banyumas #Survey SDI dan RNI



11 Nov 2023 14.47.10
7,377870S 109,012540E
Kecamatan Gumelar
#NO RUAS 277 #STA 7+500
#Kab. Banyumas #Survey SDI dan RNI

LOKASI : STA 7+440

KONDISI PERKERASAN : Rusak Berat

LEBAR PERKERASAN : 3 M

CATATAN : Aspal

LOKASI : STA 7+500

KONDISI PERKERASAN : Sedang

LEBAR PERKERASAN : 3 M

CATATAN : Aspal

NO. RUAS	NAMA RUAS	DPU KABUPATEN BANYUMAS	PETUGAS SURVEY	HALAMAN
277	CIBANGKONG - CIHONJE			43

FOTO SURVEY KONDISI JALAN TAHUN 2023

RUAS JALAN : CIBANGKONG - CIHONJE



11 Nov 2023 14.48.05
7,378455S 109,012343E
Kecamatan Gumelar
#NO RUAS 277 #STA 7+600
#Kab. Banyumas #Survey SDI dan RNI



11 Nov 2023 14.48.56
7,379245S 109,012047E
Kecamatan Gumelar
#NO RUAS 277 #STA 7+700
#Kab. Banyumas #Survey SDI dan RNI

LOKASI : STA 7+600

KONDISI PERKERASAN : Rusak Ringan

LEBAR PERKERASAN : 3 M

CATATAN : Aspal

LOKASI : STA 7+700

KONDISI PERKERASAN : Sedang

LEBAR PERKERASAN : 4 M

CATATAN : Aspal

NO. RUAS	NAMA RUAS	DPU KABUPATEN BANYUMAS	PETUGAS SURVEY	HALAMAN
277	CIBANGKONG - CIHONJE			44

FOTO SURVEY KONDISI JALAN TAHUN 2023

RUAS JALAN : CIBANGKONG - CIHONJE



11 Nov 2023 14.50.07
7,379853S 109,011707E
Kecamatan Gumelar
#NO RUAS 277 #STA 7+800
#Kab. Banyumas #Survey SDI dan RNI



11 Nov 2023 14.50.33
7,379917S 109,011527E
Kecamatan Gumelar
#NO RUAS 277 #STA 7+810
#Kab. Banyumas #Survey SDI dan RNI

LOKASI : STA 7+800

KONDISI PERKERASAN : Rusak Ringan

LEBAR PERKERASAN : 4 M

CATATAN : Aspal

LOKASI : STA 7+810

KONDISI PERKERASAN : Sedang

LEBAR PERKERASAN : 4 M

CATATAN : Aspal

NO. RUAS	NAMA RUAS	DPU KABUPATEN BANYUMAS	PETUGAS SURVEY	HALAMAN
277	CIBANGKONG - CIHONJE			45

FOTO SURVEY KONDISI JALAN TAHUN 2023

RUAS JALAN : CIBANGKONG - CIHONJE



11 Nov 2023 14.51.19
7,380218S 109,010715E
Kecamatan Gumelar
#NO RUAS 277 #STA 7+900
#Kab. Banyumas #Survey SDI dan RNI



11 Nov 2023 14.53.39
7,379830S 109,009748E
Kecamatan Gumelar
#NO RUAS 277 #STA 8+000
#Kab. Banyumas #Survey SDI dan RNI

LOKASI : STA 7+900

KONDISI PERKERASAN : Sedang

LEBAR PERKERASAN : 4 M

CATATAN : Aspal

LOKASI : STA 8+000

KONDISI PERKERASAN : Rusak Berat

LEBAR PERKERASAN : 4 M

CATATAN : Aspal

NO. RUAS	NAMA RUAS	DPU KABUPATEN BANYUMAS	PETUGAS SURVEY	HALAMAN
277	CIBANGKONG - CIHONJE			46

FOTO SURVEY KONDISI JALAN TAHUN 2023					
RUAS JALAN : CIBANGKONG - CIHONJE					
 					
LOKASI :	STA	8+080	LOKASI :	STA	8+100
KONDISI PERKERASAN	:	Sedang	KONDISI PERKERASAN	:	Sedang
LEBAR PERKERASAN	:	4 M	LEBAR PERKERASAN	:	4 M
CATATAN	:	Aspal	CATATAN	:	Aspal
NO. RUAS	NAMA RUAS	DPU KABUPATEN BANYUMAS	PETUGAS SURVEY	HALAMAN	
277	CIBANGKONG - CIHONJE			47	

FOTO SURVEY KONDISI JALAN TAHUN 2023					
RUAS JALAN : CIBANGKONG - CIHONJE					
 					
LOKASI :	STA	8+200	LOKASI :	STA	8+300
KONDISI PERKERASAN	:	Rusak Ringan	KONDISI PERKERASAN	:	Rusak Ringan
LEBAR PERKERASAN	:	4 M	LEBAR PERKERASAN	:	4 M
CATATAN	:	Aspal	CATATAN	:	Aspal
NO. RUAS	NAMA RUAS	DPU KABUPATEN BANYUMAS	PETUGAS SURVEY	HALAMAN	
277	CIBANGKONG - CIHONJE			48	

FOTO SURVEY KONDISI JALAN TAHUN 2023

RUAS JALAN : CIBANGKONG - CIHONJE



11 Nov 2023 14.57.38
7,380500S 109,007430E
Kecamatan Gumelar
#NO RUAS 277 #STA 8+400
#Kab. Banyumas #Survey SDI dan RNI



11 Nov 2023 14.58.24
7,380707S 109,006502E
Kecamatan Gumelar
#NO RUAS 277 #STA 8+500
#Kab. Banyumas #Survey SDI dan RNI

LOKASI : STA 8+400

KONDISI PERKERASAN : Sedang

LEBAR PERKERASAN : 4 M

CATATAN : Aspal

LOKASI : STA 8+500

KONDISI PERKERASAN : Rusak Ringan

LEBAR PERKERASAN : 4 M

CATATAN : Aspal

NO. RUAS	NAMA RUAS	DPU KABUPATEN BANYUMAS	PETUGAS SURVEY	HALAMAN
277	CIBANGKONG - CIHONJE			49

FOTO SURVEY KONDISI JALAN TAHUN 2023

RUAS JALAN : CIBANGKONG - CIHONJE



11 Nov 2023 14.59.09
7,381333S 109,006387E
Kecamatan Gumelar
#NO RUAS 277 #STA 8+600
#Kab. Banyumas #Survey SDI dan RNI



11 Nov 2023 15.00.00
7,381688S 109,005772E
#NO RUAS 277 #STA 8+700
#Kab. Banyumas #Survey SDI dan RNI

LOKASI : STA 8+600

KONDISI PERKERASAN : Rusak Ringan

LEBAR PERKERASAN : 4 M

CATATAN : Aspal

LOKASI : STA 8+700

KONDISI PERKERASAN : Rusak Ringan

LEBAR PERKERASAN : 4 M

CATATAN : Aspal

NO. RUAS	NAMA RUAS	DPU KABUPATEN BANYUMAS	PETUGAS SURVEY	HALAMAN
277	CIBANGKONG - CIHONJE			50

FOTO SURVEY KONDISI JALAN TAHUN 2023

RUAS JALAN : CIBANGKONG - CIHONJE



11 Nov 2023 15.00.42
7,381688S 109,005057E
Kecamatan Gumelar
#NO RUAS 277 #STA 8+800
#Kab. Banyumas #Survey SDI dan RNI



11 Nov 2023 15.01.30
7,381873S 109,004648E
Kecamatan Gumelar
#NO RUAS 277 #STA 8+830
#Kab. Banyumas #Survey SDI dan RNI

LOKASI : STA 8+800

KONDISI PERKERASAN : Rusak Ringan

LEBAR PERKERASAN : 4 M

CATATAN : Aspal

LOKASI : STA 8+830

KONDISI PERKERASAN : Rusak Ringan

LEBAR PERKERASAN : 4 M

CATATAN : Aspal

NO. RUAS	NAMA RUAS	DPU KABUPATEN BANYUMAS	PETUGAS SURVEY	HALAMAN
277	CIBANGKONG - CIHONJE			51

FOTO SURVEY KONDISI JALAN TAHUN 2023

RUAS JALAN : CIBANGKONG - CIHONJE



11 Nov 2023 15.02.06
7,382433S 109,004530E
Kecamatan Gumelar
#NO RUAS 277 #STA 8+900
#Kab. Banyumas #Survey SDI dan RNI



11 Nov 2023 15.04.32
7,382413S 109,004105E
Kecamatan Gumelar
#NO RUAS 277 #STA 9+000
#Kab. Banyumas #Survey SDI dan RNI

LOKASI : STA 8+900

KONDISI PERKERASAN : Rusak Ringan

LEBAR PERKERASAN : 4 M

CATATAN : Aspal

LOKASI : STA 9+000

KONDISI PERKERASAN : Sedang

LEBAR PERKERASAN : 4 M

CATATAN : Aspal

NO. RUAS	NAMA RUAS	DPU KABUPATEN BANYUMAS	PETUGAS SURVEY	HALAMAN
277	CIBANGKONG - CIHONJE			52

FOTO SURVEY KONDISI JALAN TAHUN 2023

RUAS JALAN : CIBANGKONG - CIHONJE



11 Nov 2023 15.05.12
7,382615S 109,003267E
Kecamatan Gumelar
#NO RUAS 277 #STA 9+100
#Kab. Banyumas #Survey SDI dan RNI



11 Nov 2023 15.06.11
7,382963S 109,003117E
Kecamatan Gumelar
#NO RUAS 277 #STA 9+120
#Kab. Banyumas #Survey SDI dan RNI

LOKASI : STA 9+100

KONDISI PERKERASAN : Rusak Ringan

LEBAR PERKERASAN : 4 M

CATATAN : Aspal

LOKASI : STA 9+120

KONDISI PERKERASAN : Baik

LEBAR PERKERASAN : 4 M

CATATAN : Aspal

NO. RUAS	NAMA RUAS	DPU KABUPATEN BANYUMAS	PETUGAS SURVEY	HALAMAN
277	CIBANGKONG - CIHONJE			53

FOTO SURVEY KONDISI JALAN TAHUN 2023

RUAS JALAN : CIBANGKONG - CIHONJE



11 Nov 2023 15.06.41
7,383447S 109,002760E
Kecamatan Gumelar
#NO RUAS 277 #STA 9+200
#Kab. Banyumas #Survey SDI dan RNI



11 Nov 2023 15.07.02
7,383510S 109,002702E
Kecamatan Gumelar
#NO RUAS 277 #STA 9+210
#Kab. Banyumas #Survey SDI dan RNI

LOKASI : STA 9+200

KONDISI PERKERASAN : Rusak Berat

LEBAR PERKERASAN : 4 M

CATATAN : Aspal

LOKASI : STA 9+210

KONDISI PERKERASAN : Baik

LEBAR PERKERASAN : 4 M

CATATAN : Aspal

NO. RUAS	NAMA RUAS	DPU KABUPATEN BANYUMAS	PETUGAS SURVEY	HALAMAN
277	CIBANGKONG - CIHONJE			54

FOTO SURVEY KONDISI JALAN TAHUN 2023

RUAS JALAN : CIBANGKONG - CIHONJE



11 Nov 2023 15.08.33
7,384290S 109,002242E
#NO RUAS 277 #STA 9+300
#Kab. Banyumas #Survey SDI dan RNI



11 Nov 2023 15.09.46
7,384468S 109,001822E
#NO RUAS 277 #STA 9+330
#Kab. Banyumas #Survey SDI dan RNI

LOKASI : STA 9+300

KONDISI PERKERASAN : Sedang

LEBAR PERKERASAN : 4 M

CATATAN : Aspal

LOKASI : STA 9+330

KONDISI PERKERASAN : Rusak Berat

LEBAR PERKERASAN : 4 M

CATATAN : Aspal

NO. RUAS	NAMA RUAS	DPU KABUPATEN BANYUMAS	PETUGAS SURVEY	HALAMAN
277	CIBANGKONG - CIHONJE			55

FOTO SURVEY KONDISI JALAN TAHUN 2023

RUAS JALAN : CIBANGKONG - CIHONJE



11 Nov 2023 15.10.29
7,384613S 109,001312E
Kecamatan Gumelar
#NO RUAS 277 #STA 9+400
#Kab. Banyumas #Survey SDI dan RNI



11 Nov 2023 15.11.08
7,384793S 109,000928E
Kecamatan Gumelar
#NO RUAS 277 #STA 9+450
#Kab. Banyumas #Survey SDI dan RNI

LOKASI : STA 9+400

KONDISI PERKERASAN : Sedang

LEBAR PERKERASAN : 4.5 M

CATATAN : Beton

LOKASI : STA 9+450

KONDISI PERKERASAN : Sedang

LEBAR PERKERASAN : 4 M

CATATAN : Aspal

NO. RUAS	NAMA RUAS	DPU KABUPATEN BANYUMAS	PETUGAS SURVEY	HALAMAN
277	CIBANGKONG - CIHONJE			56

FOTO SURVEY KONDISI JALAN TAHUN 2023

RUAS JALAN : CIBANGKONG - CIHONJE



11 Nov 2023 15.11.54
7,385003S 109,000495E
Kecamatan Gumelar
#NO RUAS 277 #STA 9+500
#Kab. Banyumas #Survey SDI dan RNI



11 Nov 2023 15.12.34
7,385062S 108,999543E
Kecamatan Gumelar
#NO RUAS 277 #STA 9+600
#Kab. Banyumas #Survey SDI dan RNI

LOKASI : STA 9+500

KONDISI PERKERASAN : Baik

LEBAR PERKERASAN : 4 M

CATATAN : Aspal

LOKASI : STA 9+600

KONDISI PERKERASAN : Rusak Berat

LEBAR PERKERASAN : 4 M

CATATAN : Aspal

NO. RUAS	NAMA RUAS	DPU KABUPATEN BANYUMAS	PETUGAS SURVEY	HALAMAN
277	CIBANGKONG - CIHONJE			57

FOTO SURVEY KONDISI JALAN TAHUN 2023

RUAS JALAN : CIBANGKONG - CIHONJE



11 Nov 2023 15.13.53
7,385327S 108,999090E
Kecamatan Gumelar
#NO RUAS 277 #STA 9+660
#Kab. Banyumas #Survey SDI dan RNI



11 Nov 2023 15.14.37
7,385562S 108,998772E
Kecamatan Gumelar
#NO RUAS 277 #STA 9+700
#Kab. Banyumas #Survey SDI dan RNI

LOKASI : STA 9+660

KONDISI PERKERASAN : Baik

LEBAR PERKERASAN : 4 M

CATATAN : Aspal

LOKASI : STA 9+700

KONDISI PERKERASAN : Rusak Berat

LEBAR PERKERASAN : 4 M

CATATAN : Aspal

NO. RUAS	NAMA RUAS	DPU KABUPATEN BANYUMAS	PETUGAS SURVEY	HALAMAN
277	CIBANGKONG - CIHONJE			58

FOTO SURVEY KONDISI JALAN TAHUN 2023

RUAS JALAN : CIBANGKONG - CIHONJE



11 Nov 2023 15.15.20
7,385752S 108,998482E
Kecamatan Gumelar
#NO RUAS 277 #STA 9+750
#Kab. Banyumas #Survey SDI dan RNI

LOKASI : STA 9+750

KONDISI PERKERASAN : Baik

LEBAR PERKERASAN : 4 M

CATATAN : Aspal



11 Nov 2023 15.15.51
7,385773S 108,997938E
Kecamatan Gumelar
#NO RUAS 277 #STA 9+800
#Kab. Banyumas #Survey SDI dan RNI

LOKASI : STA 9+800

KONDISI PERKERASAN : Baik

LEBAR PERKERASAN : 4 M

CATATAN : Aspal

NO. RUAS	NAMA RUAS	DPU KABUPATEN BANYUMAS	PETUGAS SURVEY	HALAMAN
277	CIBANGKONG - CIHONJE			59

FOTO SURVEY KONDISI JALAN TAHUN 2023

RUAS JALAN : CIBANGKONG - CIHONJE



11 Nov 2023 15.16.27
7,385545S 108,997177E
Kecamatan Gumelar
#NO RUAS 277 #STA 9+900
#Kab. Banyumas #Survey SDI dan RNI

LOKASI : STA 9+900

KONDISI PERKERASAN : Sedang

LEBAR PERKERASAN : 4 M

CATATAN : Aspal



11 Nov 2023 15.18.23
7,385340S 108,996167E
Kecamatan Gumelar
#NO RUAS 277 #STA 10+000
#Kab. Banyumas #Survey SDI dan RNI

LOKASI : STA 10+000

KONDISI PERKERASAN : Baik

LEBAR PERKERASAN : 4 M

CATATAN : Aspal

NO. RUAS	NAMA RUAS	DPU KABUPATEN BANYUMAS	PETUGAS SURVEY	HALAMAN
277	CIBANGKONG - CIHONJE			60

FOTO SURVEY KONDISI JALAN TAHUN 2023

RUAS JALAN : CIBANGKONG - CIHONJE



11 Nov 2023 15.19.03
7,384883S 108,995390E
Kecamatan Gumelar
#NO RUAS 277 #STA 10+100
#Kab. Banyumas #Survey SDI dan RNI

LOKASI : STA 10+100

KONDISI PERKERASAN : Rusak Ringan

LEBAR PERKERASAN : 4 M

CATATAN : Aspal



11 Nov 2023 15.19.51
7,384130S 108,994965E
Kecamatan Gumelar
#NO RUAS 277 #STA 10+200
#Kab. Banyumas #Survey SDI dan RNI

LOKASI : STA 10+200

KONDISI PERKERASAN : Baik

LEBAR PERKERASAN : 4 M

CATATAN : Aspal

NO. RUAS	NAMA RUAS	DPU KABUPATEN BANYUMAS	PETUGAS SURVEY	HALAMAN
277	CIBANGKONG - CIHONJE			61

FOTO SURVEY KONDISI JALAN TAHUN 2023

RUAS JALAN : CIBANGKONG - CIHONJE



11 Nov 2023 15.20.22
7,384263S 108,994200E
Kecamatan Gumelar
#NO RUAS 277 #STA 10+300
#Kab. Banyumas #Survey SDI dan RNI

LOKASI : STA 10+300

KONDISI PERKERASAN : Baik

LEBAR PERKERASAN : 4 M

CATATAN : Aspal



11 Nov 2023 15.21.03
7,384388S 108,993670E
Kecamatan Gumelar
#NO RUAS 277 #STA 10+350
#Kab. Banyumas #Survey SDI dan RNI

LOKASI : STA 10+350

KONDISI PERKERASAN : Rusak Berat

LEBAR PERKERASAN : 4 M

CATATAN : Aspal

NO. RUAS	NAMA RUAS	DPU KABUPATEN BANYUMAS	PETUGAS SURVEY	HALAMAN
277	CIBANGKONG - CIHONJE			62

FOTO SURVEY KONDISI JALAN TAHUN 2023

RUAS JALAN : CIBANGKONG - CIHONJE



LOKASI : STA 10+400

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 3 M
CATATAN : Aspal

LOKASI : STA 10+450

KONDISI PERKERASAN : Rusak Berat
LEBAR PERKERASAN : 3 M
CATATAN : Aspal

NO. RUAS	NAMA RUAS	DPU KABUPATEN BANYUMAS	PETUGAS SURVEY	HALAMAN
277	CIBANGKONG - CIHONJE			63

FOTO SURVEY KONDISI JALAN TAHUN 2023

RUAS JALAN : CIBANGKONG - CIHONJE



LOKASI : STA 10+500

KONDISI PERKERASAN : Rusak Berat
LEBAR PERKERASAN : 3 M
CATATAN : Aspal

LOKASI : STA 10+550

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 3 M
CATATAN : Aspal

NO. RUAS	NAMA RUAS	DPU KABUPATEN BANYUMAS	PETUGAS SURVEY	HALAMAN
277	CIBANGKONG - CIHONJE			64

FOTO SURVEY KONDISI JALAN TAHUN 2023

RUAS JALAN : CIBANGKONG - CIHONJE



LOKASI : STA 10+600

KONDISI PERKERASAN : Baik

LEBAR PERKERASAN : 3 M

CATATAN : Aspal



LOKASI : STA 10+700

KONDISI PERKERASAN : Baik

LEBAR PERKERASAN : 3 M

CATATAN : Aspal

NO. RUAS	NAMA RUAS	DPU KABUPATEN BANYUMAS	PETUGAS SURVEY	HALAMAN
277	CIBANGKONG - CIHONJE			65

FOTO SURVEY KONDISI JALAN TAHUN 2023

RUAS JALAN : CIBANGKONG - CIHONJE



LOKASI : STA 10+800

KONDISI PERKERASAN : Rusak Berat

LEBAR PERKERASAN : 3 M

CATATAN : Aspal



LOKASI : STA 10+900

KONDISI PERKERASAN : Sedang


LEBAR PERKERASAN : 3 M

CATATAN : Aspal

NO. RUAS	NAMA RUAS	DPU KABUPATEN BANYUMAS	PETUGAS SURVEY	HALAMAN
277	CIBANGKONG - CIHONJE			66

FOTO SURVEY KONDISI JALAN TAHUN 2023

RUAS JALAN : CIBANGKONG - CIHONJE



LOKASI : STA 11+000

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 3 M
CATATAN : Aspal

LOKASI : STA 11+050

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 3 M
CATATAN : Aspal

NO. RUAS	NAMA RUAS	DPU KABUPATEN BANYUMAS	PETUGAS SURVEY	HALAMAN
277	CIBANGKONG - CIHONJE			67

FOTO SURVEY KONDISI JALAN TAHUN 2023

RUAS JALAN : CIBANGKONG - CIHONJE



LOKASI : STA 11+100

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 3 M
CATATAN : Aspal

LOKASI : STA 11+170

KONDISI PERKERASAN : Rusak Berat
LEBAR PERKERASAN : 3 M
CATATAN : Aspal

NO. RUAS	NAMA RUAS	DPU KABUPATEN BANYUMAS	PETUGAS SURVEY	HALAMAN
277	CIBANGKONG - CIHONJE			68

FOTO SURVEY KONDISI JALAN TAHUN 2023

RUAS JALAN : CIBANGKONG - CIHONJE



LOKASI : STA 11+200

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 3 M
CATATAN : Aspal



LOKASI : STA 11+300

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 3 M
CATATAN : Aspal

NO. RUAS	NAMA RUAS	DPU KABUPATEN BANYUMAS	PETUGAS SURVEY	HALAMAN
277	CIBANGKONG - CIHONJE			69

FOTO SURVEY KONDISI JALAN TAHUN 2023

RUAS JALAN : CIBANGKONG - CIHONJE



LOKASI : STA 11+400

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 3 M
CATATAN : Aspal



LOKASI : STA 11+500

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 3 M
CATATAN : Aspal

NO. RUAS	NAMA RUAS	DPU KABUPATEN BANYUMAS	PETUGAS SURVEY	HALAMAN
277	CIBANGKONG - CIHONJE			70

FOTO SURVEY KONDISI JALAN TAHUN 2023

RUAS JALAN : CIBANGKONG - CIHONJE



11 Nov 2023 15.35.04
7,386135S 108,984237E
Kecamatan Gumelar
#NO RUAS 277 #STA 11+600
#Kab. Banyumas #Survey SDI dan RNI



11 Nov 2023 15.35.56
7,386190S 108,983807E
Kecamatan Gumelar
#NO RUAS 277 #STA 11+700
#Kab. Banyumas #Survey SDI dan RNI

LOKASI : STA 11+600

KONDISI PERKERASAN : Sedang

LEBAR PERKERASAN : 3 M

CATATAN : Aspal

LOKASI : STA 11+700

KONDISI PERKERASAN : Sedang

LEBAR PERKERASAN : 3 M

CATATAN : Aspal

NO. RUAS	NAMA RUAS	DPU KABUPATEN BANYUMAS	PETUGAS SURVEY	HALAMAN
277	CIBANGKONG - CIHONJE			71

FOTO SURVEY KONDISI JALAN TAHUN 2023

RUAS JALAN : CIBANGKONG - CIHONJE



11 Nov 2023 15.36.37
7,386272S 108,983562E
Kecamatan Gumelar
#NO RUAS 277 #STA 11+800
#Kab. Banyumas #Survey SDI dan RNI

LOKASI : STA 11+800

KONDISI PERKERASAN : Sedang

LEBAR PERKERASAN : 3 M

CATATAN : Aspal

NO. RUAS	NAMA RUAS	DPU KABUPATEN BANYUMAS	PETUGAS SURVEY	HALAMAN
277	CIBANGKONG - CIHONJE			72