

FOTO SURVEY KONDISI JALAN TAHUN 2023														
RUAS JALAN : KARANGTALUN KIDUL - KARANGTALUN LOR														
 8 Nov 2023 14.03.58 7,48853S 109,10342E #NO RUAS 305 STA 0+000 #Survey SDI dan RNI #Kab.Banyumas  8 Nov 2023 14.05.22 7,48759S 109,10345E #NO RUAS 305 STA 0+100 #Survey SDI dan RNI #Kab.Banyumas														
LOKASI : STA 0+000 LOKASI : STA 0+100														
KONDISI PERKERASAN : Rusak Berat KONDISI PERKERASAN : Rusak Berat														
LEBAR PERKERASAN : 2,8 M LEBAR PERKERASAN : 2,8 M														
CATATAN : Aspal CATATAN : Aspal														
<table border="1" style="width: 100%; border-collapse: collapse;"><tr><td style="width: 15%;">NO. RUAS</td><td style="width: 30%;">NAMA RUAS</td><td style="width: 30%;">DPU KABUPATEN BANYUMAS</td><td style="width: 20%;">PETUGAS SURVEY</td><td style="width: 5%;">HALAMAN</td></tr><tr><td style="text-align: center;">305</td><td style="text-align: center;">KARANGTALUN KIDUL - KARANGTALUN LOR</td><td></td><td></td><td style="text-align: center;">1</td></tr></table>					NO. RUAS	NAMA RUAS	DPU KABUPATEN BANYUMAS	PETUGAS SURVEY	HALAMAN	305	KARANGTALUN KIDUL - KARANGTALUN LOR			1
NO. RUAS	NAMA RUAS	DPU KABUPATEN BANYUMAS	PETUGAS SURVEY	HALAMAN										
305	KARANGTALUN KIDUL - KARANGTALUN LOR			1										

FOTO SURVEY KONDISI JALAN TAHUN 2023														
RUAS JALAN : KARANGTALUN KIDUL - KARANGTALUN LOR														
 8 Nov 2023 14.05.59 7,48680S 109,10348E Kecamatan Purwojati #NO RUAS 305 STA 0+200 #Survey SDI dan RNI #Kab.Banyumas  8 Nov 2023 14.06.38 7,48609S 109,10349E Kecamatan Purwojati #NO RUAS 305 STA 0+260 #Survey SDI dan RNI #Kab.Banyumas														
LOKASI : STA 0+200 LOKASI : STA 0+260														
KONDISI PERKERASAN : Rusak Berat KONDISI PERKERASAN : Rusak Ringan														
LEBAR PERKERASAN : 2,8 M LEBAR PERKERASAN : 2,8 M														
CATATAN : Aspal CATATAN : Aspal														
<table border="1" style="width: 100%; border-collapse: collapse;"><tr><td style="width: 15%;">NO. RUAS</td><td style="width: 30%;">NAMA RUAS</td><td style="width: 30%;">DPU KABUPATEN BANYUMAS</td><td style="width: 20%;">PETUGAS SURVEY</td><td style="width: 5%;">HALAMAN</td></tr><tr><td style="text-align: center;">305</td><td style="text-align: center;">KARANGTALUN KIDUL - KARANGTALUN LOR</td><td></td><td></td><td style="text-align: center;">2</td></tr></table>					NO. RUAS	NAMA RUAS	DPU KABUPATEN BANYUMAS	PETUGAS SURVEY	HALAMAN	305	KARANGTALUN KIDUL - KARANGTALUN LOR			2
NO. RUAS	NAMA RUAS	DPU KABUPATEN BANYUMAS	PETUGAS SURVEY	HALAMAN										
305	KARANGTALUN KIDUL - KARANGTALUN LOR			2										

FOTO SURVEY KONDISI JALAN TAHUN 2023

RUAS JALAN : KARANGTALUN KIDUL - KARANGTALUN LOR



8 Nov 2023 14.06.59
7,48560S 109,10352E
Kecamatan Purwojati
#NO RUAS 305 STA 0+300
#Survey SDI dan RNI #Kab.Banyumas



8 Nov 2023 14.07.22
7,48489S 109,10352E
Kecamatan Purwojati
#NO RUAS 305 STA 0+400
#Survey SDI dan RNI #Kab.Banyumas

LOKASI : STA 0+300

KONDISI PERKERASAN : Baik

LEBAR PERKERASAN : 4 M

CATATAN : Aspal

LOKASI : STA 0+400

KONDISI PERKERASAN : Sedang

LEBAR PERKERASAN : 4 M

CATATAN : Aspal

NO. RUAS	NAMA RUAS	DPU KABUPATEN BANYUMAS	PETUGAS SURVEY	HALAMAN
305	KARANGTALUN KIDUL - KARANGTALUN LOR			3

FOTO SURVEY KONDISI JALAN TAHUN 2023

RUAS JALAN : KARANGTALUN KIDUL - KARANGTALUN LOR



8 Nov 2023 14.07.49
7,48406S 109,10355E
Kecamatan Purwojati
#NO RUAS 305 STA 0+500
#Survey SDI dan RNI #Kab.Banyumas



8 Nov 2023 14.08.15
7,48313S 109,10360E
#NO RUAS 305 STA 0+600
#Survey SDI dan RNI #Kab.Banyumas

LOKASI : STA 0+500

KONDISI PERKERASAN : Baik

LEBAR PERKERASAN : 4 M

CATATAN : Aspal

LOKASI : STA 0+600

KONDISI PERKERASAN : Baik

LEBAR PERKERASAN : 4 M

CATATAN : Aspal

NO. RUAS	NAMA RUAS	DPU KABUPATEN BANYUMAS	PETUGAS SURVEY	HALAMAN
305	KARANGTALUN KIDUL - KARANGTALUN LOR			4

FOTO SURVEY KONDISI JALAN TAHUN 2023

RUAS JALAN : KARANGTALUN KIDUL - KARANGTALUN LOR



8 Nov 2023 14.08.45
7,48220S 109,10361E
Kecamatan Purwojati
#NO RUAS 305 STA 0+700
#Survey SDI dan RNI #Kab.Banyumas



8 Nov 2023 14.09.08
7,48142S 109,10364E
Kecamatan Purwojati
#NO RUAS 305 STA 0+800
#Survey SDI dan RNI #Kab.Banyumas

LOKASI : STA 0+700

KONDISI PERKERASAN : Baik

LEBAR PERKERASAN : 4 M

CATATAN : Aspal

LOKASI : STA 0+800

KONDISI PERKERASAN : Baik

LEBAR PERKERASAN : 4 M

CATATAN : Aspal

NO. RUAS	NAMA RUAS	DPU KABUPATEN BANYUMAS	PETUGAS SURVEY	HALAMAN
305	KARANGTALUN KIDUL - KARANGTALUN LOR			5

FOTO SURVEY KONDISI JALAN TAHUN 2023

RUAS JALAN : KARANGTALUN KIDUL - KARANGTALUN LOR



8 Nov 2023 14.09.56
7,48063S 109,10366E
#NO RUAS 305 STA 0+880
#Survey SDI dan RNI #Kab.Banyumas

LOKASI : STA 0+880

KONDISI PERKERASAN : Baik

LEBAR PERKERASAN : 5 M

CATATAN : Aspal

NO. RUAS	NAMA RUAS	DPU KABUPATEN BANYUMAS	PETUGAS SURVEY	HALAMAN
305	KARANGTALUN KIDUL - KARANGTALUN LOR			6