

FOTO SURVEY KONDISI JALAN TAHUN 2023

RUAS JALAN : PAMIJEN-REMPOAH (SOKAWERA)



LOKASI : STA 0+000

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 4 M
CATATAN : Aspal


LOKASI : STA 0+100

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 4 M
CATATAN : Aspal

NO. RUAS	NAMA RUAS	DPU KABUPATEN BANYUMAS	PETUGAS SURVEY	HALAMAN
54	PAMIJEN-REMPOAH (SOKAWERA)			1

FOTO SURVEY KONDISI JALAN TAHUN 2023

RUAS JALAN : PAMIJEN-REMPOAH (SOKAWERA)



LOKASI : STA 0+200

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 3.5 M
CATATAN : Aspal

LOKASI : STA 0+300

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 3.5 M
CATATAN : Aspal

NO. RUAS	NAMA RUAS	DPU KABUPATEN BANYUMAS	PETUGAS SURVEY	HALAMAN
54	PAMIJEN-REMPOAH (SOKAWERA)			2

FOTO SURVEY KONDISI JALAN TAHUN 2023

RUAS JALAN : PAMIJEN-REMPOAH (SOKAWERA)



LOKASI : STA 0+400

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 3.5 M
CATATAN : Aspal

LOKASI : STA 0+500

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 3.5 M
CATATAN : Aspal

NO. RUAS	NAMA RUAS	DPU KABUPATEN BANYUMAS	PETUGAS SURVEY	HALAMAN
54	PAMIJEN-REMPOAH (SOKAWERA)			3

FOTO SURVEY KONDISI JALAN TAHUN 2023

RUAS JALAN : PAMIJEN-REMPOAH (SOKAWERA)



LOKASI : STA 0+600

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 3.5 M
CATATAN : Aspal

LOKASI : STA 0+700

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 3.5 M
CATATAN : Aspal

NO. RUAS	NAMA RUAS	DPU KABUPATEN BANYUMAS	PETUGAS SURVEY	HALAMAN
54	PAMIJEN-REMPOAH (SOKAWERA)			4