

FOTO SURVEY KONDISI JALAN TAHUN 2024

RUAS JALAN : JL. NUSAMANGIR - SIBALUNG



LOKASI :	STA	0+000	LOKASI :	STA	0+100
KONDISI PERKERASAN	:	Rusak Ringan	KONDISI PERKERASAN	:	Sedang
LEBAR PERKERASAN	:	2.5 M	LEBAR PERKERASAN	:	2.5 M
CATATAN	:	Aspal	CATATAN	:	Aspal

NO. RUAS	NAMA RUAS	DPU KABUPATEN BANYUMAS	PETUGAS SURVEY	HALAMAN
238	JL. NUSAMANGIR - SIBALUNG			1

FOTO SURVEY KONDISI JALAN TAHUN 2024

RUAS JALAN : JL. NUSAMANGIR - SIBALUNG



LOKASI :	STA	0+200	LOKASI :	STA	0+300
KONDISI PERKERASAN	:	Sedang	KONDISI PERKERASAN	:	Rusak Ringan
LEBAR PERKERASAN	:	2.5 M	LEBAR PERKERASAN	:	2.5 M
CATATAN	:	Aspal	CATATAN	:	Aspal

NO. RUAS	NAMA RUAS	DPU KABUPATEN BANYUMAS	PETUGAS SURVEY	HALAMAN
238	JL. NUSAMANGIR - SIBALUNG			2

FOTO SURVEY KONDISI JALAN TAHUN 2024

RUAS JALAN : JL. NUSAMANGIR - SIBALUNG



LOKASI : STA 0+400

KONDISI PERKERASAN : Sedang

LEBAR PERKERASAN : 2.5 M

CATATAN : Aspal

LOKASI : STA 0+500

KONDISI PERKERASAN : Sedang

LEBAR PERKERASAN : 3 M

CATATAN : Aspal

NO. RUAS	NAMA RUAS	DPU KABUPATEN BANYUMAS	PETUGAS SURVEY	HALAMAN
238	JL. NUSAMANGIR - SIBALUNG			3

FOTO SURVEY KONDISI JALAN TAHUN 2024

RUAS JALAN : JL. NUSAMANGIR - SIBALUNG



LOKASI : STA 0+600

KONDISI PERKERASAN : Rusak Berat

LEBAR PERKERASAN : 3 M

CATATAN : Aspal

LOKASI : STA 0+700

KONDISI PERKERASAN : Rusak Berat

LEBAR PERKERASAN : 3 M

CATATAN : Aspal

NO. RUAS	NAMA RUAS	DPU KABUPATEN BANYUMAS	PETUGAS SURVEY	HALAMAN
238	JL. NUSAMANGIR - SIBALUNG			4

FOTO SURVEY KONDISI JALAN TAHUN 2024

RUAS JALAN : JL. NUSAMANGIR - SIBALUNG



LOKASI : STA 0+800

KONDISI PERKERASAN : Rusak Berat

LEBAR PERKERASAN : 3 M

CATATAN : Aspal

LOKASI : STA 0+900

KONDISI PERKERASAN : Rusak Berat

LEBAR PERKERASAN : 3 M

CATATAN : Aspal

NO. RUAS	NAMA RUAS	DPU KABUPATEN BANYUMAS	PETUGAS SURVEY	HALAMAN
238	JL. NUSAMANGIR - SIBALUNG			5

FOTO SURVEY KONDISI JALAN TAHUN 2024

RUAS JALAN : JL. NUSAMANGIR - SIBALUNG



LOKASI : STA 1+000

KONDISI PERKERASAN : Rusak Berat

LEBAR PERKERASAN : 3 M

CATATAN : Aspal

LOKASI : STA 1+100

KONDISI PERKERASAN : Rusak Berat

LEBAR PERKERASAN : 3 M

CATATAN : Aspal

NO. RUAS	NAMA RUAS	DPU KABUPATEN BANYUMAS	PETUGAS SURVEY	HALAMAN
238	JL. NUSAMANGIR - SIBALUNG			6

FOTO SURVEY KONDISI JALAN TAHUN 2024

RUAS JALAN : JL. NUSAMANGIR - SIBALUNG



LOKASI : STA 1+200

KONDISI PERKERASAN : Rusak Ringan

LEBAR PERKERASAN : 3 M

CATATAN : Aspal



LOKASI : STA 1+300

KONDISI PERKERASAN : Rusak Ringan

LEBAR PERKERASAN : 3 M

CATATAN : Aspal

NO. RUAS	NAMA RUAS	DPU KABUPATEN BANYUMAS	PETUGAS SURVEY	HALAMAN
238	JL. NUSAMANGIR - SIBALUNG			7

FOTO SURVEY KONDISI JALAN TAHUN 2024

RUAS JALAN : JL. NUSAMANGIR - SIBALUNG



LOKASI : STA 1+400

KONDISI PERKERASAN : Rusak Berat

LEBAR PERKERASAN : 3 M

CATATAN : Aspal



LOKASI : STA 1+500

KONDISI PERKERASAN : Rusak Berat

LEBAR PERKERASAN : 3 M

CATATAN : Aspal

NO. RUAS	NAMA RUAS	DPU KABUPATEN BANYUMAS	PETUGAS SURVEY	HALAMAN
238	JL. NUSAMANGIR - SIBALUNG			8

FOTO SURVEY KONDISI JALAN TAHUN 2024

RUAS JALAN : JL. NUSAMANGIR - SIBALUNG



LOKASI : STA 1+600

KONDISI PERKERASAN : Rusak Ringan

LEBAR PERKERASAN : 3 M

CATATAN : Aspal



LOKASI : STA 1+700

KONDISI PERKERASAN : Rusak Ringan

LEBAR PERKERASAN : 3 M

CATATAN : Aspal

NO. RUAS	NAMA RUAS	DPU KABUPATEN BANYUMAS	PETUGAS SURVEY	HALAMAN
238	JL. NUSAMANGIR - SIBALUNG			9

FOTO SURVEY KONDISI JALAN TAHUN 2024

RUAS JALAN : JL. NUSAMANGIR - SIBALUNG



LOKASI : STA 1+800

KONDISI PERKERASAN : Rusak Berat

LEBAR PERKERASAN : 3 M

CATATAN : Aspal



LOKASI : STA 1+860

KONDISI PERKERASAN : Rusak Ringan

LEBAR PERKERASAN : 3 M

CATATAN : Aspal

NO. RUAS	NAMA RUAS	DPU KABUPATEN BANYUMAS	PETUGAS SURVEY	HALAMAN
238	JL. NUSAMANGIR - SIBALUNG			10