

FOTO SURVEY KONDISI JALAN TAHUN 2024
RUAS JALAN : CIKAWUNG - CIBANGKONG



LOKASI : STA 0+000


KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 3.5 M
CATATAN : Aspal

LOKASI : STA 0+100

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 3.5 M
CATATAN : Aspal

NO. RUAS	NAMA RUAS	DPU KABUPATEN BANYUMAS	PETUGAS SURVEY	HALAMAN
286	CIKAWUNG - CIBANGKONG			1

FOTO SURVEY KONDISI JALAN TAHUN 2024
RUAS JALAN : CIKAWUNG - CIBANGKONG



LOKASI : STA 0+200

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 3.5 M
CATATAN : Aspal

LOKASI : STA 0+300

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 3 M
CATATAN : Aspal

NO. RUAS	NAMA RUAS	DPU KABUPATEN BANYUMAS	PETUGAS SURVEY	HALAMAN
286	CIKAWUNG - CIBANGKONG			2

FOTO SURVEY KONDISI JALAN TAHUN 2024

RUAS JALAN : CIKAWUNG - CIBANGKONG



LOKASI : STA 0+400

KONDISI PERKERASAN : Baik

LEBAR PERKERASAN : 3 M

CATATAN : Aspal

LOKASI : STA 0+500

KONDISI PERKERASAN : Baik

LEBAR PERKERASAN : 3 M

CATATAN : Aspal

NO. RUAS	NAMA RUAS	DPU KABUPATEN BANYUMAS	PETUGAS SURVEY	HALAMAN
286	CIKAWUNG - CIBANGKONG			3

FOTO SURVEY KONDISI JALAN TAHUN 2024

RUAS JALAN : CIKAWUNG - CIBANGKONG



LOKASI : STA 0+550

KONDISI PERKERASAN : Rusak Berat

LEBAR PERKERASAN : 3.5 M

CATATAN : Aspal

LOKASI : STA 0+600

KONDISI PERKERASAN : Rusak Berat

LEBAR PERKERASAN : 3.5 M

CATATAN : Aspal

NO. RUAS	NAMA RUAS	DPU KABUPATEN BANYUMAS	PETUGAS SURVEY	HALAMAN
286	CIKAWUNG - CIBANGKONG			4

FOTO SURVEY KONDISI JALAN TAHUN 2024

RUAS JALAN : CIKAWUNG - CIBANGKONG



LOKASI : STA 0+700

KONDISI PERKERASAN : Baik

LEBAR PERKERASAN : 3.5 M

CATATAN : Aspal

LOKASI : STA 0+800

KONDISI PERKERASAN : Baik

LEBAR PERKERASAN : 3.5 M

CATATAN : Aspal

NO. RUAS	NAMA RUAS	DPU KABUPATEN BANYUMAS	PETUGAS SURVEY	HALAMAN
286	CIKAWUNG - CIBANGKONG			5

FOTO SURVEY KONDISI JALAN TAHUN 2024

RUAS JALAN : CIKAWUNG - CIBANGKONG



LOKASI : STA 0+900

KONDISI PERKERASAN : Baik

LEBAR PERKERASAN : 3 M

CATATAN : Beton

LOKASI : STA 1+000

KONDISI PERKERASAN : Baik

LEBAR PERKERASAN : 3.5 M

CATATAN : Beton

NO. RUAS	NAMA RUAS	DPU KABUPATEN BANYUMAS	PETUGAS SURVEY	HALAMAN
286	CIKAWUNG - CIBANGKONG			6

FOTO SURVEY KONDISI JALAN TAHUN 2024

RUAS JALAN : CIKAWUNG - CIBANGKONG



LOKASI : STA 1+050

KONDISI PERKERASAN : Baik

LEBAR PERKERASAN : 3.5 M

CATATAN : Aspal



LOKASI : STA 1+100

KONDISI PERKERASAN : Rusak Ringan

LEBAR PERKERASAN : 3.5 M

CATATAN : Aspal

NO. RUAS	NAMA RUAS	DPU KABUPATEN BANYUMAS	PETUGAS SURVEY	HALAMAN
286	CIKAWUNG - CIBANGKONG			7

FOTO SURVEY KONDISI JALAN TAHUN 2024

RUAS JALAN : CIKAWUNG - CIBANGKONG



LOKASI : STA 1+200

KONDISI PERKERASAN : Sedang

LEBAR PERKERASAN : 3.5 M

CATATAN : Aspal



LOKASI : STA 1+300

KONDISI PERKERASAN : Baik

LEBAR PERKERASAN : 3.5 M

CATATAN : Aspal

NO. RUAS	NAMA RUAS	DPU KABUPATEN BANYUMAS	PETUGAS SURVEY	HALAMAN
286	CIKAWUNG - CIBANGKONG			8

FOTO SURVEY KONDISI JALAN TAHUN 2024

RUAS JALAN : CIKAWUNG - CIBANGKONG



LOKASI : STA 1+350

LOKASI : STA 1+400

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 3.5 M
CATATAN : Aspal

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 3.5 M
CATATAN : Aspal

NO. RUAS	NAMA RUAS	DPU KABUPATEN BANYUMAS	PETUGAS SURVEY	HALAMAN
286	CIKAWUNG - CIBANGKONG			10